

Inspection Report

Leader

PRODUCT DESCRIPTION				
		Inspection Number	√ 1	<u></u> 3
		Inspection Date 03.N		v.2014
		Inspector Sun		ny R
		Inspection Location	Shan tou , ChaoYang	
		Factory	SAFEER	
		Responsible	MR.Ch	narlies
Supplier	GALENFIX	Order Total Quant	ity	2880
Item	LC282B	Quantity Ready on Inspe	ction Date	2880
PI Number	BRA 377	Pieces to Inspect According	to AQL II 2.5	125

Factory cooperation Factory organization		Inspector's oneedleion on the factory
Factory employees helped during all the inspection	Factory is big-sized.	Factory is untidy,Need to improve and to enhancethe quality awareness

OVERALL INSPECTION RESULT:	Passed
----------------------------	--------

INSPECTION RESULT SUMMARY					
	Result	sult Findings/Remarks			
INSPECTION LIST	Passed, according to AQL standard		CRITICAL	MAJOR	MINOR
		Found	0	4	7
		Maximum Allowed	0	7	10
		Most serious defects found:			d:
			Loose s	tain bow	



TESTS				
QUANTITY	ok	100% of the order is finished		
PRODUCT COLOR	N/A	No fabric sample to ref.		
ARTWORKS N/A		No PPS to ref.		
PRODUCT DIMENSIONS	With error	Within acceptable limit		
PACKING & PACKAGING ok 100% has been packaged		100% has been packaged		
SHIPPING MARKS	ok	OK		

OTHER REMARKS

Factory didn't provide sample to check, No special requirement from Leader.

INSPECTION STANDARDS				
Inspection type	Final Inspection Before Shipment			
Sampling standard	AQL II 2.5			
Workmanship : AQL for Cri/Maj/Min	Critical = Not Allowed // Major = 2.5 // Minor = 4.0			
Sampling size according to AQL	125			
Pieces Inspected	125			
Cartons in this order	40			
Cartons Available	40			
Cartons Inspected	4			
Inspected Cartons Reference Number	3,36,29,17.			

QUANTITY CRITERIA				
Expected Result	Result Actual Finding / Comments			
100% of the order should be finished	OK 100% finished			
Pieces Already Packed	2880			
Pieces not Packed	0	Pieces not Finis	shed	0



GENERAL PICTURES

Factory / Warehouse









Boxes







Opening Boxes

Shipneedleg Marks



		PHOLES		
(Indicated particular S.A. MINISTRACTION DISTRICT STATE MINISTRACTION DISTRICT STATE MINISTRACTION DISTRICT STATE MINISTRACTION STATE MINISTRACTION STATE MINISTRACTION MINISTRACTI	P1 31104-01002	PROSE, CONSTRUE, R. STAL	64 - Carr 21710-010	Leader
Bulance Injurie and Color.	ant.			Certan Sandfra
Department -	Arts	de Rumbers name LCHOS	Experies SALEMIALA.	Decardus stry
f-+	43	- 0	- 41	44
Consumerys 404				
Sold Per Sine	1	1	4	4
Total of Feet Ion 78s See Total of Feet Ion 78s See	12		EFR dones Weight: T	Age Distriction

Labels / Tags














PRODUCTS PICTURES



MEASUREMENT TABLE



MEASUREMENT CONCLUSION

Within acceptable limit



DEFECT DESCRIPTION	MAJOR	MINOR
Loose stain bow	2	0






DEFECT DESCRIPTION	MAJOR	MINOR
Dirty mark :1 // Exposed seam allowance :1	2	0





DEFECT DESCRIPTION	MAJOR	MINOR
Uncut seam allowance :1 // Slanting on Bartack :2	0	3









DEFECT DESCRIPTION	MAJOR	MINOR
uncut thread end	0	4









INSPECTION SUMMARY		
DEFECTS	MAJOR	MINOR
Loose stain bow	2	0
Dirty mark :1 // Exposed seam allowance :1	2	0
Uncut seam allowance :1 // Slanting on Bartack :2	0	3
uncut thread end	0	4
TOTAL	4	7

CLIENT SPECIAL REQUEST FOR THIS ORDER



Chent dian t sena any special requirement for this order

SUGGESTIONS FOR LEADER AND FOR SUPPLIER

none

FACTORY REPORT (Signed by the Factory's Responsible Person) ChinaInvest&AsiaInvest W05/755 86331570 驗貨報告 頭標: Usufformmel 颜色: Pob 日期: 3-100-14 28fo fu 总箱数: 40 問題描述 大點 小點 的视的破落 141 少的以打老 3 142 4 後 次 21治病提供批为以及重点粮水

Original signature from factory's responsible person accepting ChinaInvest inspection results

Cuayo

拒絕

擔保

IMPORTANT NOTES

THE ABOVE RESULT(S) REFLECT(S) CHINAINVEST'S FINDINGS AT THE TIME AND PLACE OF INSPECTION. THIS REPORT DOES NOT RELEASE THE BUYER OR SELLER FROM CONTRACTUAL RESPONSIBILITIES, NOR DOES IT PREJUDICE THE BUYER'S



RIGHT OF CLAIM TOWARD THE SELLER/SUPPLIER FOR COMPENSATION FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING THE INSPECTION OR OCCURRING ANYTIME THEREAFTER.