


How to create Surface Weight data

N2H-11781 - [ADS] Surface Weight computation FINI

The below steps are used to create data for surface weight computation:

- Create an Elementary Part with 3D part and save.
- Select a plane and click on the *Positioned sketch* tool under the Model tab then create a sketch with any  **closed shape**.




Positioned Sketch icon

- Add padding to it by selecting the sketch in the model tree or in the main view and click on the *Pad* tool under the Model tab. Chose a length and validate the padding by clicking on "OK".




Generative Shape Design

- Click on the 3D Compass (top left) , search and select **Generative Shape Design** App
- Select the 3D part created by double clicking on it on the model tree.



- In the Toolbar, select **Essentials** tab and click on **Geometrical Set** command.
- Enter a name for the Geometrical Set and click on OK.

The image shows the 'Insert Geometrical Set' dialog box. It has a title bar with a question mark and a close button. The dialog contains three fields: 'Name:' with an empty text box, 'Parent:' with a dropdown menu showing '3D Shape00016786 A.1', and 'Features:' with an empty list box. At the bottom, there are 'OK' and 'Cancel' buttons.

Insert Geometrical Set ? X

Name:

Parent: 3D Shape00016786 A.1 ▼


Features:

OK Cancel


Two ways of creating Surface:

First Method:


Click on the geometrical set created and click on **Extrude** command



Select 2 lines which are adjacent and click on ok.




Right click on the **Extrude** created **Properties -> Feature Properties** Enter the required Surface name in Feature Name field. Surface name should be in the format with prefix '**Surface_**' followed by the **PT Code** value (The **PT code** exists in **properties >>tab references >> PT Code**, of the data created (EP, SA, etc) choose someone of this for rename the surface). Ex: **Surface_AA451**




Second Method:

Click on the geometrical set created and click on **Extract** command under **Essentials** tab and then click on the surface to be selected and OK.



Right click on the **Extract** created Properties -> Feature Properties Enter the required Surface name in Feature Name field. Surface name should be in the format with prefix 'Surface_' followed by the PT Code value. Ex: Surface_AA451



Save the dataset created(Ctrl+S)