注: 1. H6/n5和H7/p6在基本尺寸小于或等于3mm和H8/r7在小于或等于100mm时,为过渡配合。

2. 带底纹的配合为优先配合。

											轴										
基准孔	a	b	С	d	е	f	g	h	js	k	m	n	р	r	S	t	u	V	X	у	Z
	间隙配合							过渡配合			过盈配合										
Н6						<u>H6</u>	<u>H6</u>	<u>H6</u>	<u>H6</u>	<u>H6</u>	<u>H6</u>	<u>H6</u>	<u>H6</u>	<u>H6</u>	<u>H6</u>	<u>H6</u>					
						f5	g5	h5	js5	k5	m5	n5	р5	r5	s5	t5					
Н7						<u>H7</u>	<u>H7</u>	<u>H7</u>	<u>H7</u>	<u>H7</u>	<u>H7</u>	<u>H7</u>	<u>H7</u>	<u>H7</u>	<u>H7</u>	<u>H7</u>	<u>H7</u>	<u>H7</u>	<u>H7</u>	<u>H7</u>	<u>H7</u>
						f6	g6	h6	js6	k6	m6	n6	р6	r6	s6	t6	u6	v6	х6	у6	z6
Н8					<u>H8</u>	<u>H8</u>	<u>H8</u>	<u>H8</u>	<u>H8</u>	<u>H8</u>	<u>H8</u>	<u>H8</u>	<u>H8</u>	<u>H8</u>	<u>H8</u>	<u>H8</u>	<u>H8</u>				
					е7	f7	g7	h7	js7	k7	m7	n7	р7	r7	s7	t7	u7				
				<u>H8</u>	<u>H8</u>	<u>H8</u>		<u>H8</u>													
				d8	е8	f8		h8													
Н9			<u>H9</u>	<u>H9</u>	<u>H9</u>	<u>H9</u>		<u>H9</u>													
			с9	d9	е9	f9		h9													
H10			<u>H10</u>	<u>H10</u>				<u>H10</u>													
			c10	d10				h10													
H11	<u>H11</u>	<u>H11</u>	<u>H11</u>	<u>H11</u>				<u>H11</u>													
	a11	b11	c11	d11				h11													
H12		<u>H12</u>						<u>H12</u>													
		b12						h12													