		上偏差(es)															
轴的基本偏差		d	е	f	g	h		js	k	m	n	р	r	S	t	u	
公差等级		6至18															
基本尺寸/mm		符 号															
大于	至	-	-	-	-	-			+	+	+	+	+	+	+	+	
3150	3550	580	320	160		0					290	290	680	1600	2400	3600	
3550	4000											290	720	1750	2600	4000	
4000	4500	640	350	175		0						360	840	2000	3000	4600	
4500	5000						偏差= ±IT/2						900	2200	3300	5000	
5000	5600	720	380	190				±IT/2				440	1050	2500	3700	5600	
5600	6300												1100	2800	4100	6400	
6300	7100	800	420	210		0						540	1300	3200	4700	7200	
7100	8000												1400	3500	5200	8000	
8000	9000	880	460	230		0						680	1650	4000	6000	9000	
9000	10000	000											1750	4400	6600	10000	
大于	至	+	+	+	+		空格			-	-	-	-	-	-	-	
基本尺	基本尺寸/mm		符号														
公差	公差等级		6 <u>至</u> 18														
孔的基本偏差		D	Е	F	G	Н		JS	K	М	N	Р	R	S	Т	U	
		下偏差(EI)							上偏差(ES)								