## **HV-G/HW-G Series Comparator Wiring.**

**Note:** dc supply can be either positive common or negative common to suit the installation. Customer Relays to be maximum 50Vdc 100mA.

**HI Relay** is used for Final Weight, On during batch, turns off when target reached. (Used for Dribble Feed if using OK Relay for Main Feed).

**OK Relay** is used for Prelim Weight, **Hi** minus **OK** setting. On during batch, turns off when target reached. (Used for Main Feed if OK is set to any value other than zero).

LO Relay is used for Zero Band detection to ensure system is ready to start the batch.

