


BEFORE AND AFTER OPTIMISATION

Check the Optimisation Results

Current status of the site





Optimized Green Space Layout

The optimized green space layout maximizes the visual exposure to greenery for pedestrians, improving environmental comfort and enhancing the walking experience within the community. The total green space area after optimization closely matches the planned target (6476 m²), ensuring regulatory compliance without unnecessary land use or resource wastage. What's more, the layout guarantees that each designated green area boundary contains a reasonable proportion of green space, avoiding underutilized or barren zones and promoting spatial equity.

Green Visibility: 0.972
Green Area: 5239.824263


Planned Area: 6476
Area Difference: 1236.175



In the previous computer vision analysis of the perceived comfort of the elderly, it was found that the relationship between green visibility and the comfort of the elderly showed a positive. After analyzing the site, it was found that the residential area did not achieve a good level of comfort. The current situation of the site has scattered green space distribution in the form of patches, and is not evenly distributed on the path.


INBETWEEN GENERATED RESULTS COMPARISONS

Revealing the Optimal Solution of Comfort



EVALUATE SOLUTIONS

Check the Optimisation Results



FUTURE WORK & LIMITATIONS

- Lack of Parameter Calibration in View Analysis
- No Control Over Spatial Continuity or Shape of Green Areas
- No Integration with Environmental or Behavioral Data:
The optimization is static and does not respond to external data such as sunlight, wind, or pedestrian movement. Future work could integrate real-time or context-aware inputs to enable adaptive green space planning.
- Limited Evaluation Dimensions:
The optimization currently considers only visual exposure and area compliance. Other important aspects—such as accessibility, usability, sunlight exposure, and acoustic buffering—are not yet incorporated into the fitness evaluation.