AI Automobile Diagnosis Report

Vehicle Information

Registration	TN-42-U-3009
Manufacturer	Honda
Model	city
Year	2024
Mileage	0 km

Diagnosis Results

Predicted Fault	Starter Problem
Confidence	28.0%
Severity	HIGH
Symptoms	Engine vibration, High fuel consumption, Whistling sound

Possible Causes

- Battery discharge
- Starter motor failure
- Alternator issue

Recommended Action

Check battery voltage and connections. If problem persists, consult a technician.

DISCLAIMER: This report is generated by an AI-assisted prototype for educational purposes. It is NOT a professional mechanical diagnosis. Please consult a qualified technician before performing any repairs or driving a vehicle with critical faults.