Break				
1	60			
2	65			
3	67			
4	69			
5	71			
6	73			

SPI					
SCK	28				
SDO	31				
SDI	33				
CS	38				

MOTORS								
PHASES	+U	+V	+W	-U	-V	-W		
Motor 1	7	2	144	10	3	1		
Motor 2	142	138	136	143	141	137		
Motor 3	133	129	127	135	132	128		
Motor 4	125	121	119	126	124	120		
Motor 5	114	112	100	115	113	111		
Motor 6	105	103	98	106	104	101		