

PW Exhaustive HS

Vehicle Damage Assessment Report

Report No. E6D00A98
Date: 14.05.2026

Vehicle Information

Manufacturer	Audi
Type	A6
Subtype	A6 3.0 TDI quattro
VIN	WAUZZZ4F58N035435
KBA Number	0588/AAS
First Registration	07.05.2007
Last Registration	15.03.2024
Power	171 kW / 233 PS
Displacement	2.967 ccm
Vehicle Type	Sedan
Seats	5

Accident Information

Date	15.03.2026
Accident Scene	Kreuzung B1/B2, Berlin-Mitte

Claimant

Name	Thomas Müller
Company	Autohaus Müller GmbH
Address	Friedrichstraße 100, 10117, Berlin
Email	thomas@autohaus-mueller.de
Phone	+49 30 123456
License Plate	FÜ B 147

Opponent

Name	Stefan Braun
Company	Logistik Braun GmbH
Insurance Company	HUK-COBURG
Insurance Number	HUK-2026-789012

Visits

Type	Other
------	-------

Address	Friedrichstraße 100, 10117, Berlin
Date	20.03.2026
Expert	Dr. Hans Turnes

Expert Opinion

Expert Name	Dr. Hans Turnes
File Number	HB-2026-001
Case Date	16.03.2026
Issued Date	01.04.2026
Mediator	Mark Cooper

Vehicle Condition

General Condition	Well maintained
Body Condition	Minor cosmetic
Interior Condition	Clean, no structural damage.
Paint Type	Uni (2 Schicht)
Paint Finish	Original manufacturer paint
Paint Condition	Good
Vehicle Color	Silver Metallic
Driving Ability	Roadworthy
Mileage	142.850 km
Estimated Mileage	143.200 km
Next MOT	01.06.2027
Special Features	Navigation, Heated Seats, Bose Premium Audio
Notes	Fahrzeug in gutem allgemeinem Zustand.
Previous Damage Reported	Stoßstange hinten 2024 repariert
Existing Damage (Not Reported)	Keine
Subsequent Damage	Keine

Damage Markers

#1: Right side panel scratches | Severity: moderate | Repair: Clean and assess the scratch depth. If scratches have not penetrated to bare metal, perform paint correction and polishing. If deeper, sand affected area, apply primer, base coat, and clear coat. Treat any corrosion spots before repainting.

Tires

Set 1

Valuation & Calculation

Vehicle Value

Repair

Wheel Alignment	Not required
Body Measurements	Not required
Body Paint	Spot repair
Plastic Repair	Yes
Repair Method	Conventional body repair with paint correction
Damage Class	I
Risks	Paint may have penetrated into scratches requiring deeper surface preparation; possible minor dent underneath paint damage

Loss of Use

Repair Time	1 days
-------------	--------

Invoice

Invoice Number	GH-5718-2026
Invoice Date	03.04.2026

#	Description	Qty	Rate	Amount
1	Grundhonorar Gutachten	1	362,00 €	362,00 €
			Net Total	362,00 €
			VAT (19%)	68,78 €
			Gross Total	430,78 €

Photo Documentation

Damage Photos (2)



Visible paint damage and scratches on the right side panel surface. The affected area shows multiple scratch marks with a greenish-yellow discol-

Identification (2)



Documents (1)

