

PW Exhaustive KG

Vehicle Damage Assessment Report

Report No. BD011329

Date: 14.05.2026

Vehicle Information

Manufacturer	Opel
Type	Corsa
Subtype	Corsa D 1.2 16V
VIN	W0L0SDL0884123456
KBA Number	0035/AHM
First Registration	15.04.2008
Last Registration	15.08.2023
Power	59 kW / 80 PS
Displacement	1.229 ccm
Vehicle Type	Compact

Accident Information

Date	28.12.2025
Accident Scene	Frankenstraße, Nürnberg

Claimant

Name	Klaus Schneider
Company	Müller Transport GmbH
Address	Hauptstraße 25, 90402, Nürnberg
Email	klaus.schneider@mueller-transport.de
Phone	+49 911 445566
License Plate	N ZJ 1975

Opponent

Name	Hans Wagner
Company	Spedition Wagner
Insurance Company	Allianz
Insurance Number	ALZ-2025-998877

Visits

Type	Other
Address	Hauptstraße 25, 90402, Nürnberg

Date	30.12.2025
Expert	Dr. Hans Turnes

Expert Opinion

Expert Name	Dr. Hans Turnes
File Number	KG-2025-130
Case Date	28.12.2025
Issued Date	05.01.2026
Mediator	Mark Cooper

Vehicle Condition

General Condition	Well maintained
Body Condition	Minor cosmetic
Interior Condition	Clean, no structural damage.
Paint Type	Uni (2 Schicht)
Paint Finish	Original manufacturer paint
Paint Condition	Good
Vehicle Color	Pannacotta Weiß
Driving Ability	Roadworthy
Mileage	187.300 km
Estimated Mileage	187.500 km
Next MOT	01.08.2026
Special Features	Klimaanlage, Radio CD
Notes	Kleinwagen mit normalen Gebrauchsspuren.
Previous Damage Reported	Kofferraumdeckel 2022 repariert
Existing Damage (Not Reported)	Keine
Subsequent Damage	Keine

Damage Markers

- #1: Right door panel scratches | Severity: moderate | Repair: The damaged area requires paint repair involving sanding, priming, base coat application, and clear coat refinishing. Depending on scratch depth, minor filler application may be necessary. Complete door panel repainting recommended to ensure proper color match and finish quality.
- #2: Left side panel scratches | Severity: minor | Repair: Paint surface repair through wet sanding, polishing, and buffing of the affected area. If scratches penetrate through clear coat to base coat, localized spot repair with paint blending may be necessary.

Tires

Set 1

Valuation & Calculation

Vehicle Value

Replacement Value	4.200,00 €
Residual Value	2.800,00 €
Diminution in Value	450,00 €

Repair

Wheel Alignment	Not required
Body Measurements	Not required
Body Paint	Panel repaint
Repair Method	Teilreparatur
Damage Class	II
Risks	Geringe Risiken

Loss of Use

Cost per Day	30,00 €
Repair Time	3 days
Replacement Time	7 days

Invoice

Invoice Number	GH-7153-2026
Invoice Date	08.01.2026

#	Description	Qty	Rate	Amount
1	Kurzgutachten Opel Corsa	1	225,00 €	225,00 €
			Net Total	225,00 €
			VAT (19%)	42,75 €
			Gross Total	267,75 €

Photo Documentation

Vehicle Overview (1)



A gray Opel Corsa hatchback photographed in a parking lot during winter conditions with patches of snow visible on the ground. The vehicle appears

Damage Photos (2)



The left side panel exhibits multiple surface scratches and paint abrasions visible in the central area of the panel above the wheel arch. The scratches



Visible damage to the right side door panel consisting of multiple deep scratches and paint damage. The scratches appear to have penetrated

Interior Photos (1)



Classic analog instrument cluster with three round gauges featuring warm amber lighting and red needles. The dashboard shows an odometer reading