## **Panel Cutting Patterns - Summary**

```
Mesh Statistics:
  Total Faces: 32
  Total Vertices: 60
  Total Edges: 144
  Unique Panel Types: 4

Panel Breakdown:


Panel Type 1:
    Quantity: 3
    Sides: 5
```

Panel Type 2: Quantity: 7 Sides: 5 Panel Type 3: Quantity: 2

Panel Type 4: Quantity: 20 Instructions: 3

Sides: 5

- 1. Print each panel pattern on the following pages
- 2. Cut along the solid black lines
- 3. Use the dashed red lines for seam allowance (if shown)
- 4. Edge measurements are shown in the same units as input
- 5. Assemble panels according to the 3D model



Panel Type 2 (Quantity: 7) Sides: 5, Area: 77.6533, Perimeter: 33.5912 6 6.718 4 6.718 2 6.718 0 **-**2 6.718 **-**4 6.718 -6 \_ \_\_2 6 -6 0

Panel Type 3 (Quantity: 2) Sides: 5, Area: 21.4629, Perimeter: 46.0475 6 6.718 4 2 10.870 10.870 0 10.870 **-**2 -4 6.718 -6 2 -2 Ó 6 -6

Panel Type 4 (Quantity: 20) Sides: 3, Area: 28.9840, Perimeter: 24.5443

