

Refusal of an MOT test certificate

Registration number AB12 CDE Date of test 20/02/2026

Odometer reading 44,770 miles

Test result: FAIL

Reasons for failure (major): Offside rear brake pipe corroded

Advisories: Exhaust has a minor leak

Testing station: Exe Valley Test Centre

The vehicle must not be driven until the defects are repaired.