

Quality & Safety Inspection Report — QSI-2026-0091

Quality & Safety Inspection Report. Report ID: QSI-2026-0091. Date: 05-Apr-2026.

Facility: Unit 2 Process Area. Inspector: Anita Sharma, Senior QA Engineer.

Scope: Compliance check against Factory Act 1948 and internal Quality Management System (QMS) procedure QMS-SOP-014 for pressure vessel documentation.

Finding 1: Boiler-3 pressure vessel certification renewal is due within 30 days (expires 04-May-2026). Renewal application not yet submitted. Flagged as a compliance gap requiring action before deadline.

Finding 2: Pump-101 maintenance records now up to date following bearing replacement on 12-Mar-2026 (ref Work Order WO-4521). No further action required.

Finding 3: Compressor-7 near-miss incident (22-Mar-2026, high discharge temperature trip) has been logged but the strainer inspection frequency has not yet been revised in the Preventive Maintenance schedule. Recommend reducing strainer inspection interval from 90 days to 45 days.

Overall compliance status: 2 of 3 items compliant. 1 item requires corrective action before next audit cycle.