

Maintenance Work Order Log — March 2026

Work Order WO-4521. Date: 12-Mar-2026. Equipment: Pump-101 (Centrifugal Feed Pump, Unit 3).

Reported issue: Elevated vibration levels detected during routine rounds by technician Ramesh Kumar. Vibration reading was 8.2 mm/s RMS, above the alarm threshold of 7.1 mm/s specified in the OEM manual.

Root cause identified: bearing wear on the drive-end bearing, likely due to lubrication interval exceeding the recommended 90-day cycle. Last lubrication was performed 142 days prior.

Corrective action: Drive-end bearing replaced. New bearing installed per OEM spec (SKF 6309). Lubrication schedule updated to 60-day cycle for this pump going forward, approved by supervisor Anita Sharma.

Work Order WO-4522. Date: 15-Mar-2026. Equipment: Boiler-3 (Unit 2).

Scheduled inspection under OISD-118 guidelines for pressure vessel safety. Pressure reading recorded at 12.4 bar, within the operating range of 10-14 bar. No anomalies found. Inspected by Vikram Singh.

Work Order WO-4530. Date: 22-Mar-2026. Equipment: Compressor-7 (Unit 1).

Unplanned downtime event. Compressor tripped due to high discharge temperature (98 C, threshold 90 C). Root cause: cooling water flow restriction from partially blocked strainer. Strainer cleaned, flow restored. Downtime duration: 3 hours 40 minutes. Estimated production loss: 45 units.