



Result Name



Result

Photo

| CSV ID | 02969_Label |
|---------------------------|---------------------|
| Overall Judgement | PASS |
| Inspector Override | TRUE |
| DataMatrix_Match | PASS |
| E_LatchProfile | FAIL |
| Dowel Pin | PASS |
| Alignment Pin | PASS |
| CSV ID | 02969_Connector |
| Overall Judgement | PASS |
| Inspector Override | TRUE |
| Pins Not Bent | FAIL |
| Alignment Guides | PASS |
| Cover Appearance | PASS |
| CSV ID | 02969_WedgelockDown |
| Overall Judgement | PASS |
| Inspector Override | FALSE |
| FH Screws Seated | PASS |
| FH Screws Not Black Oxide | PASS |
| PH Screws Correct | PASS |
| Chassis Rail Appearance | PASS |
| Cover Appearance | PASS |
| CSV ID | 02969_WedgelockUp |
| Overall Judgement | PASS |



| | |
|-------------------------------|------------------------|
| Inspector Override | TRUE |
| Label Present | PASS |
| Overlay Present | PASS |
| CAGE & Part Number | PASS |
| WedgeLock Damage | PASS |
| WedgeLock Retainer Lip Damage | FAIL |
| Ejector Appearance | FAIL |
| Cover Appearance | PASS |
| CSV ID | 02969_Side_EjectorUp |
| Overall Judgement | PASS |
| Inspector Override | FALSE |
| Correct Connector Screw | PASS |
| No MB-Chassis Gap | PASS |
| MB Appearance | PASS |
| WedgeLocks Legible | PASS |
| WedgeLocks Not Chipped | PASS |
| Chassis Appearance | PASS |
| CSV ID | 02969_Side_EjectorDown |
| Overall Judgement | PASS |
| Inspector Override | FALSE |
| Correct Connector Screw | PASS |
| No MB-Chassis Gap | PASS |
| MB Appearance | PASS |
| WedgeLocks Not Chipped | PASS |



P/N: PL39669 S/N: 03001

UID Grade: B (3.0)

Overall Pass/Fail: **PASS (OVERRIDDEN)**

WO24063053

11/25/2024, 14:41:24

WARNING: DUPLICATE SN DETECTED! REF TXID 8946081.0

THIS SN WAS PREVIOUSLY SENT TO CUSTOMER!

RANTEC
EXCELLENCE BY DESIGN

| | |
|--------------------|------|
| Chassis Appearance | PASS |
|--------------------|------|

P/N: PL39669 S/N: 03001

UID Grade: B (3.0)

Overall Pass/Fail: **PASS (OVERRIDDEN)**

WO24063053

11/25/2024, 14:41:24

RANTEC

EXCELLENCE BY DESIGN

WARNING: DUPLICATE SN DETECTED! REF TXID 8946081.0

THIS SN WAS PREVIOUSLY SENT TO CUSTOMER!



P/N: PL39669 S/N: 03001

UID Grade: B (3.0)

Overall Pass/Fail: **PASS (OVERRIDDEN)**



WO24063053

11/25/2024, 14:41:24

WARNING: DUPLICATE SN DETECTED! REF TXID 8946081.0

THIS SN WAS PREVIOUSLY SENT TO CUSTOMER!

RANTEC
EXCELLENCE BY DESIGN



P/N: PL39669 S/N: 03001

UID Grade: B (3.0)

Overall Pass/Fail: **PASS (OVERRIDDEN)**

WO24063053

11/25/2024, 14:41:24

WARNING: DUPLICATE SN DETECTED! REF TXID 8946081.0

THIS SN WAS PREVIOUSLY SENT TO CUSTOMER!

RANTEC
EXCELLENCE BY DESIGN

