


Micro Quadrotor Wiring Diagram

Custom 3D-Printed Micro Quadrotor with Servo Payload Release | Rev B | 2026-09-04



Legend

- VBAT — battery voltage (7.6V, 2S HV)
- Regulated 5V (RX ESP32 + servo power, from FC/ESC onboard BEC)
- Signal (SBUS, PWM)
- ESP-NOW wireless link (2.4GHz WiFi, no physical connection)

GND is common between battery, FC/ESC, motors, RX ESP32, and servo (single ground reference — no separate ground lines shown, standard practice for a build this small). Motor phase wires are soldered directly; no bullet connectors needed at this current level. 5V and PWM/SBUS signal wires run from the FC/ESC board's onboard BEC and servo pad respectively. The handheld TX ESP32 is off-board, battery-powered separately (USB power bank), and reaches the RX ESP32 only wirelessly via ESP-NOW — it has no wired connection to the drone.