




⚠ CAUTION

**SETTING OF
ATC SPEED**

Select medium or low
ATC speed mode if tool
weight exceeds 6kg.
High speed ATC mode
with heavy tool (>6 Kg)
will damage the ATC.

21V5120A425-00

⚠ DANGER



Entering enclosed
spaces during machine
operation can cause
serious injury or death.
Turn OFF main power
before opening door.

21V5120A425-00

⚠ WARNING



Improper insertion of
tool can cause the tool
to be thrown during the
ATC cycle, leading to
serious injury.
Close door fully
before ATC cycle.

21V5120A425-00

⚠ WARNING



Carelessness when
removing workpiece can
cause serious injury.
Machined edges are
sharp and can cut.
Exercise extreme care
when removing
workpiece.

21V5120A427-00