




⚠ CAUTION SETTING OF ATC SPEED Select medium or low ATC speed mode if tool weight exceeds 6kg. High speed ATC mode with heavy tool (>6 Kg) will damage the ATC. 21V5120A425-00	⚠ DANGER  Entering enclosed spaces during machine operation can cause serious injury or death. Turn OFF main power before opening door. 21V5120A425-00
⚠ WARNING  Improper insertion of tool can cause the tool to be thrown during the ATC cycle, leading to serious injury. Close door fully before ATC cycle. 21V5120A425-00	⚠ WARNING  Carelessness when removing workpiece can cause serious injury. Machined edges are sharp and can cut. Exercise extreme care when removing workpiece. 21V5120A427-00