




⚠ CAUTION

SETTING OF ATC SPEED

Select medium or low ATC speed mode if tool weight exceeds 6kg.

High speed ATC mode with heavy tool (>6 Kg) will damage the ATC.

⚠ DANGER



Entering enclosed spaces during machine operation can cause serious injury or death.

Turn OFF main power before opening door.

⚠ WARNING



Improper insertion of tool can cause the tool to be thrown during the ATC cycle, leading to serious injury.

Close door fully before ATC cycle.

⚠ WARNING



Carelessness when removing workpiece can cause serious injury.

Machined edges are sharp and can cut.

Exercise extreme care when removing workpiece.