




DANGER



Entering enclosed spaces during machine operation can cause serious injury or death.

Turn OFF main power before opening door.