




1 X-Axis Servomotor

2 Z-Axis Servomotor

3 Y-Axis Servomotor

4 X-Axis Linear Motion Guides

5 Y-Axis Linear Motion Guides

6 Z-Axis Linear Motion Guides

7 X-Axis Ball Screw

8 Y-Axis Ball Screw

9 X-Axis Feedback Scale Unit