Prince Said Ibrahim International Airport (IATA: HAH, ICAO: FMCH) (French: Aéroport international Moroni Prince Saïd Ibrahim, AIMPSI) is an international airport serving Moroni in Comoros. It is named after Prince Saïd Ibrahim. It is located north of the village of Hahaya.

Contents

1 Airlines and destinations

2 Accidents and incidents

3 References

4 External links

Airlines and destinations[edit]

Airlines Destinations

AB Aviation Anjouan, Dar es Salaam, Dzaoudzi, Moheli

Air Austral Saint-Denis de la Réunion

Air Madagascar Antananarivo, Majunga

Air Tanzania Dar es Salaam

Ethiopian Airlines 1 Addis Ababa [1]

Ewa Air Dzaoudzi

Kenya Airways Nairobi-Jomo Kenyatta

Madagasikara Airways Antananarivo, Majunga

Turkish Airlines2 Seasonal: Istanbul[2]

Notes

- ^1: Ethiopian Airlines's flight from Addis Ababa to Moroni stops in Dar es Salaam, but the airline does not have fifth freedom rights on the DAR HAH sector.
- ^2 : Turkish Airlines's flight from Moroni to Istanbul stops in Seychelles, but the airline does not have fifth freedom rights on the SEZ HAH sector.

Accidents and incidents[edit]

On 23 November 1996, Ethiopian Airlines Flight 961, a Boeing 767-200ER flying from Addis Ababa to Abidjan with several stopovers was hijacked over Ethiopia by three Ethiopians seeking asylum in Australia. The plane crash-landed in the water three hours later when it ran out of fuel. 125 of the 175 passengers and crew were killed, including the three hijackers. The pilot's initial decision to land at the airport was thwarted due to the fuel starvation.

On 30 June 2009, Yemenia Flight 626, flying from Yemen to Moroni crashed into the Indian Ocean while on final approach to the airport. 152 out of the 153 people on board were killed.[3]

On 27 November 2012 an Int'Air Îles Embraer EMB 120ER Brasilia (registration number D6-HUA) was underway from Moroni to Anjouan (both in Comoros Islands) on a charter flight with 25 passengers and 4 crew, when after taking off from Moroni's Prince Said Ibrahim International Airport it lost height, and while attempting to return to the airport, waterlanded 200 meters off the coast, about 5 km north of the airport. Local fishermen rescued everybody on board. There were only minor injuries.[4]

While the runway is considered long enough for modern jetliners, landings can still prove

difficult because of frequently changing weather conditions and the surrounding mountains of the island.[citation needed]