


On-axis $B_z(r=0, z)$



On-axis $\Delta B_z = \text{OPERA} - \text{Measured}$

