




Dim.		eters		hes
Diiii.	min	max	min	max
Α	2.19	2.38	0.086	0.094
A1	0.89	1.14	0.035	0.045
b	0.64	0.89	0.025	0.035
b1	0.76	1.14	0.030	0.045
b2	5.21	5.46	0.205	0.215
С	0.46	0.58	0.018	0.023
c1	0.46	0.58	0.018	0.023
D	5.97	6.22	0.235	0.245
E	6.35	6.73	0.250	0.265
е	2.28	BSC	0.090 BSC	
e1	4.57	BSC	0.180 BSC	
Н	17.02	17.78	0.670	0.700
L	8.89	9.65	0.350	0.380
L1	1.91	2.28	0.075	0.090
L2	0.89	1.27	0.035	0.050
L3	1.15	1.52	0.045	0.060




Dim.	Millim	eters	Inc	hes	
Dilli.	min	max	min	max	
Α	2.20	2.40	0.087	0.094	
A1	2.10	2.50	0.083	0.098	
b	0.66	0.86	0.026	0.034	
b2	-	0.96	-	0.038	
b3	5.04	5.64	0.198	0.222	
b4	4.34	BSC	0.171	BSC	
b5	0.50	BSC	0.020	BSC	
С	0.40	0.60	0.016	0.024	
D	5.90	6.30	0.232	0.248	
Е	6.40	6.80	0.252	0.268	
е	2.10	2.50	0.083	0.098	
Н	9.20	9.80	0.362	0.386	
L	0.55	1.02	0.022	0.040	
L1	2.50	2.90	0.098	0.114	
L2	0.40	0.60	0.016	0.024	
L3	0.50	0.90	0.020	0.035	
L4	0.60	1.00	0.024	0.039	
L5	0.82	1.22	0.032	0.048	
L6	0.79	0.99	0.031	0.039	
L7	0.81	1.01	0.032	0.040	
L8	0.40	0.80	0.016	0.031	
L9	1.50	BSC	0.059 BSC		
ØΡ	1.00	BSC	0.039	BSC	




Dim.	Millimeters		Inches	
Diiii.	min	max	min	max
Α	4.32	4.82	0.170	0.190
A1	1.14	1.39	0.045	0.055
A2	2.29	2.79	0.090	0.110
b	0.64	1.01	0.025	0.040
b2	1.15	1.65	0.045	0.065
О	0.35	0.56	0.014	0.022
D	14.73	16.00	0.580	0.630
Е	9.91	10.66	0.390	0.420
е	2.54	BSC	0.100 BSC	
H1	5.85	6.85	0.230	0.270
L	12.70	13.97	0.500	0.550
L1	2.79	5.84	0.110	0.230
ØΡ	3.54	4.08	0.139	0.161
Q	2.54	3.18	0.100	0.125



				•
Dim.	Millimeters		Inches	
DIIII.	min	max	min	max
Α	4.32	4.82	0.170	0.190
A1	1.14	1.39	0.045	0.055
A2	2.29	2.79	0.090	0.110
b	0.64	1.01	0.025	0.040
b2	1.15	1.65	0.045	0.065
С	0.35	0.56	0.014	0.022
D	14.73	16.00	0.580	0.630
Е	9.91	10.66	0.390	0.420
е	5.08	BSC	0.200	BSC
H1	5.85	6.85	0.230	0.270
L	12.70	13.97	0.500	0.550
L1	2.79	5.84	0.110	0.230
ØΡ	3.54	4.08	0.139	0.161
0	2 54	3 18	0.100	0.125




Dim.	Millimeters		Inches	
ווווט.	min	max	min	max
Α	4.32	4.82	0.170	0.190
A1	1.14	1.39	0.045	0.055
A2	2.29	2.79	0.090	0.110
b	0.64	1.01	0.025	0.040
С	0.38	0.64	0.015	0.025
D	14.73	15.75	0.580	0.620
D1	8.64	9.40	0.340	0.370
Е	9.91	10.54	0.390	0.415
е	1.70	BSC	0.067	BSC
k	0.00	0.36	0.000	0.014
L	25.27	26.54	0.995	1.045
L1	11.94	12.95	0.470	0.510
ØΡ	3.53	3.96	0.139	0.156




Dim.	Millim	eters	Inc	hes	
DIIII.	min	max	min	max	
Α	4.50	4.90	0.177	0.193	
A1	2.34	2.74	0.092	0.108	
A2	2.56	2.96	0.101	0.117	
b	0.70	0.90	0.028	0.035	
b1	1.27	1.47	0.050	0.058	
С	0.45	0.60	0.018	0.024	
D	15.67	16.07	0.617	0.633	
Е	9.96	10.36	0.392	0.408	
е	2.54	BSC	0.100	0 BSC	
Н	6.48	6.88	0.255	0.271	
L	12.68	13.28	0.499	0.523	
L1	3.03	3.43	0.119	0.135	
ØΡ	3.08	3.28	0.121	0.129	
Q	3.20	3.40	0.126	0.134	







Dim.	Millim	eters	Inches	
DIIII.	min	max	min	max
Α	4.50	4.90	0.177	0.193
A1	2.34	2.74	0.092	0.108
A2	2.56	2.96	0.101	0.117
b	0.70	0.90	0.028	0.035
b1	1.27	1.47	0.050	0.058
С	0.45	0.60	0.018	0.024
D	15.67	16.07	0.617	0.633
d1	0.00	1.10	0.000	0.043
Е	9.96	10.36	0.392	0.408
е	2.54	BSC	0.100 BSC	
Н	6.48	6.88	0.255	0.271
L	12.68	13.28	0.499	0.523
L1	3.03	3.43	0.119	0.135
ØΡ	3.08	3.28	0.121	0.129
Q	3.20	3.40	0.126	0.134




Dim.	Millim	eters	Inches	
Dilli.	min	max	min	max
Α	4.30	4.70	0.169	0.185
A1	2.20	2.60	0.087	0.102
b	0.70	0.90	0.028	0.035
b1	1.37	1.57	0.054	0.062
С	0.45	0.60	0.018	0.024
c1	1.25	1.40	0.049	0.055
D	9.00	9.40	0.355	0.370
D1	7.5	20	0.284	
Е	9.70	9.90	0.382	0.390
E1	7.0	00	0.276	
е	2.54	BSC	0.100	BSC
L	12.88	13.28	0.507	0.523
L1	3.00	-	0.118	-
L2	1.00	1.40	0.039	0.055




Dim.	Millim	eters	Inc	hes	
Diiii.	min	max	min	max	
Α	4.06	4.83	0.160	0.190	
A2	2.4	41	0.0	95	
b	0.51	0.99	0.020	0.039	
b2	1.14	1.40	0.045	0.055	
С	0.40	0.74	0.016	0.029	
c2	1.14	1.40	0.045	0.055	
D	8.38	9.40	0.330	0.370	
D1	8.00	8.89	0.315	0.350	
D2	2.	.5	0.098		
Е	9.65	10.41	0.380	0.410	
E1	6.22	8.50	0.245	0.335	
е	2.54	BSC	0.100 BSC		
e1	4.5	28	0.169		
L	13.00	13.60	0.512	0.535	
L1	2.90	3.10	0.114	0.122	
L2	1.02	1.68	0.040	0.066	
		mensions co			
	and/or within JEDEC standard				



Dim.	Millim	eters	Inches	
Diiii.	min	max	min	max
Α	4.30	4.70	0.169	0.185
A1	0.70	0.90	0.028	0.035
A2	2.50	3.00	0.098	0.118
b	0.90	1.20	0.035	0.047
b1	2.03	2.41	0.080	0.095
b2	1.37	1.63	0.054	0.064
С	0.70	0.90	0.028	0.035
D	14.00	15.00	0.551	0.591
D1	13.00	13.70	0.512	0.539
E	10.00	11.00	0.394	0.433
E1	8.40	8.80	0.331	0.346
е	2.54	BSC	0.100	BSC
L	13.00	14.00	0.512	0.551
L1	3.00	3.50	0.118	0.138
L2	0.90	1.30	0.035	0.051
L3	1.20	1.50	0.047	0.059




Dim.	Millim	neters	Inc	hes	
Dilli.	min	max	min	max	
Α	4.00	5.00	0.157	0.197	
A1	2.50	3.00	0.098	0.118	
A2	1.60	1.80	0.063	0.071	
b	0.90	1.30	0.035	0.051	
b2	2.35	2.55	0.093	0.100	
b4	1.25	1.65	0.049	0.065	
С	0.70	1.00	0.028	0.039	
D	15.00	16.00	0.591	0.630	
D1	12.00	13.00	0.472	0.512	
D2	1.10	1.50	0.043	0.059	
D3	14.90	15.50	0.587	0.610	
E	10.00	11.00	0.394	0.433	
E1	7.50	8.50	0.295	0.335	
е	2.54	BSC	0.100	BSC	
L	13.00	14.50	0.512	0.571	
L1	3.00	3.50	0.118	0.138	
T°	42.5	47.5			
W	-	0.10	-	0.004	




Dim.	Millim	eters	Inches	
Dilli.	min	max	min	max
Α	4.00	5.00	0.157	0.197
A1	2.50	3.00	0.098	0.118
A2	1.60	1.80	0.063	0.071
b	0.90	1.30	0.035	0.051
b2	1.25	1.65	0.049	0.065
b4	2.35	2.55	0.093	0.100
С	0.70	1.00	0.028	0.039
D	15.00	16.00	0.591	0.630
D1	12.00	13.00	0.472	0.512
D2	1.10	1.50	0.043	0.059
D3	14.90	15.50	0.587	0.610
E	10.00	11.00	0.394	0.433
E1	7.50	8.50	0.295	0.335
е	5.08	BSC	0.200	BSC
L	13.00	14.50	0.512	0.571
L1	3.00	3.50	0.118	0.138
T°	42.5	47.5		
W	-	0.10	-	0.004



Dimensions in mm and inches (1 mm = 0.0394")




Dim.	Millimeter		Inches	
Dim.	min	max	min	max
Α	4.06	4.83	0.160	0.190
A1	typ.	0.10	typ. 0	0.004
b	0.51	0.99	0.020	0.039
b2	1.14	1.40	0.045	0.055
С	0.40	0.74	0.016	0.029
c2	1.14	1.40	0.045	0.055
D	8.38	9.40	0.330	0.370
D1	8.00	8.89	0.315	0.350
Е	9.65	10.41	0.380	0.410
E1	6.22	8.13	0.245	0.320
е	2,54	BSC	0,100 BSC	
Н	14.61	15.88	0.575	0.625
L	1.78	2.79	0.070	0.110
L1	1.02	1.68	0.040	0.066
W	typ. 0.02	0.040	typ. 0.0008	0.002




Dim.	Millin	neter	Inches	
חוווט.	min	max	min	max
Α	4.06	4.83	0.160	0.190
A1	typ.	0.10	typ. C	0.004
b	0.51	0.99	0.020	0.039
b2	1.14	1.40	0.045	0.055
С	0.40	0.74	0.016	0.029
c2	1.14	1.40	0.045	0.055
D	8.38	9.40	0.330	0.370
D1	8.00	8.89	0.315	0.350
Е	9.65	10.41	0.380	0.410
E1	6.22	8.13	0.245	0.320
е	2,54	BSC	0,100 BSC	
Н	14.61	15.88	0.575	0.625
L	1.78	2.79	0.070	0.110
L1	1.02	1.68	0.040	0.066
W	typ. 0.02	0.040	typ. 0.0008	0.002

Weight = 2.5 g



D:	Millim	eters	Inches	
Dim.	min	max	min	max
Α	4.06	4.83	0.160	0.190
A1	typ (0.10	typ 0	.004
A2	2.4	41	0.0	95
b	0.51	0.99	0.020	0.039
b2	1.14	1.40	0.045	0.055
С	0.40	0.74	0.016	0.029
c2	1.14	1.40	0.045	0.055
D	8.38	9.40	0.330	0.370
D1	8.00	8.89	0.315	0.350
D2	2.	.5	0.098	
Е	9.65	10.41	0.380	0.410
E1	6.22	8.50	0.245	0.335
е	2.54	BSC	0.100 BSC	
e1	4.2	28	0.169	
Н	14.61	15.88	0.575	0.625
L	1.78	2.79	0.070	0.110
L2	1.02	1.68	0.040	0.066
W	typ 0.02	0.040	typ 0.0008	0.002
			onform with	
and/or within JEDEC standard				




Weight = 1.5 g

X012a TO-263 (5)


Dim.	Millimeter		Inches	
Diiii.	min	max	min	max
Α	4.20	4.80	0.160	0.190
A1	2.10	2.70	0.083	0.106
b	0.60	0.99	0.024	0.039
С	0.40	0.70	0.016	0.028
c2	1.20	1.40	0.047	0.055
D	8.80	9.50	0.346	0.374
D1	6.60	7.20	0.260	0.283
Е	9.65	10.30	0.380	0.406
E1	7.50	8.20	0.295	0.323
е	1.70	BSC	0.067	BSC
L	14.80	15.80	0.583	0.622
L1	2.24	2.84	0.088	0.112
L2	1.00	1.40	0.039	0.067
L3	1.20	1.70	0.047	0.067






Dim.	Millin	neter	Incl	hes
Diiii.	min	max	min	max
Α	4.20	4.60	0.165	0.181
A1	2.45	2.75	0.096	0.108
b	0.65	0.90	0.026	0.035
С	0.40	0.60	0.016	0.024
c2	1.14	1.40	0.045	0.055
D	8.38	8.64	0.330	0.340
D1	6.10	6.35	0.240	0.250
Е	10.00	10.30	0.394	0.406
E1	7.34	8.00	0.290	0.315
е	1.27	BSC	0.050	BSC
L	14.73	15.75	0.580	0.620
L1	2.24	2.84	0.088	0.112
L2	1.35	1.55	0.053	0.061

X013 PLUS220™ (SMD) Weight = 2 g




Dim.	Millin	neter	Inches	
Dim.	min	max	min	max
Α	4.30	4.70	0.169	0.185
A1	0.70	0.90	0.028	0.035
A2	2.50	3.00	0.098	0.118
A3	0.00	0.25	0.000	0.010
b	0.90	1.20	0.035	0.047
b1	2.03	2.41	0.080	0.095
b2	1.37	1.63	0.054	0.064
С	0.70	0.90	0.028	0.035
D	14.00	15.00	0.551	0.591
D1	13.00	13.70	0.512	0.539
Е	10.00	11.00	0.394	0.433
E1	8.40	8.80	0.331	0.346
е	5.08	BSC	0.200	BSC
L	5.30	5.80	0.209	0.228
L1	3.00	3.50	0.118	0.138
L2	0.90	1.30	0.035	0.051
L3	1.20	1.50	0.047	0.059
L4	1.00	1.50	0.039	0.059







Dim.	Millin	neter	Inc	hes
Diiii.	min	max	min	max
Α	4.70	5.30	0.185	0.209
A1	2.21	2.59	0.087	0.102
A2	1.50	2.49	0.059	0.098
b	0.99	1.40	0.039	0.055
b2	1.65	2.39	0.065	0.094
b4	2.59	3.43	0.102	0.135
С	0.38	0.89	0.015	0.035
D	20.79	21.45	0.819	0.845
D1	13.07	-	0.515	-
D2	0.51	1.35	0.020	0.053
Е	15.48	16.24	0.610	0.640
E1	13.45	-	0.53	•
E2	4.31	5.48	0.170	0.216
е	5.45	BSC	0.215 BSC	
L	19.80	20.30	0.078	0.800
L1	-	4.49	-	0.177
ØΡ	3.55	3.65	0.140	0.144
Ø P1	-	7.39	-	0.290
Q	5.38	6.19	0.212	0.244
S	6.14	BSC	0.242	BSC




Dim.	Millin	neter	Incl	hes
Dim.	min	max	min	max
Α	4.70	5.30	0.185	0.209
A1	2.21	2.59	0.087	0.102
A2	1.50	2.49	0.059	0.098
b	0.99	1.40	0.039	0.055
b2	1.65	2.39	0.065	0.094
b4	2.59	3.43	0.102	0.135
С	0.38	0.89	0.015	0.035
D	20.79	21.45	0.819	0.845
D1	13.07	-	0.515	-
D2	0.51	1.35	0.020	0.053
Е	15.48	16.24	0.610	0.640
E1	13.45	-	0.530	-
E2	4.31	5.48	0.170	0.216
е	10.90	BSC	0.430 BSC	
L	19.80	20.30	0.078	0.800
L1	-	4.49	-	0.177
ØР	3.55	3.65	0.140	0.144
Ø P1	-	7.39	•	0.290
Q	5.38	6.19	0.212	0.244
S	6.14	BSC	0.242	BSC




Dim.	Millin	neter	Inches	
Dim.	min	max	min	max
Α	4.83	5.21	0.190	0.205
A1	2.29	2.54	0.090	0.100
A2	1.91	2.16	0.075	0.085
b	1.14	1.40	0.045	0.055
b1	1.90	2.10	0.075	0.084
b2	2.92	3.12	0.115	0.123
С	0.60	0.80	0.024	0.031
D	20.80	21.34	0.819	0.840
Е	15.75	16.13	0.620	0.635
е	5.45	BSC	0.215 BSC	
L	19.80	20.30	0.078	0.800
L1	3.80	4.30	0.150	0.170
Q	5.60	6.20	0.220	0.244
R	4.32	4.83	0.170	0.190



Dim.	Millin	neter	Inches			
Dilli.	min	max	min	max		
Α	4.83	5.21	0.190	0.205		
A1	2.29	2.54	0.090	0.100		
A2	1.91	2.16	0.075	0.085		
b	1.14	1.40	0.045	0.055		
b2	1.91	2.20	0.075	0.087		
b4	2.92	3.24	0.115	0.128		
С	0.61	0.83	0.024	0.033		
D	20.80	21.34	0.819	0.840		
D1	15.75	16.26	0.620	0.640		
D2	1.65	2.15	0.065	0.085		
D3	20.30	20.70	0.799	0.815		
Е	15.75	16.13	0.620	0.635		
E1	13.21	13.72	0.520	0.540		
е	5.45	BSC	0.215	BSC		
L	19.81	20.60	0.780	0.811		
L1	3.81	4.38	0.150	0.172		
Q	5.59	6.20	0.220	0.244		
R	4.25	5.50	0.167	0.217		
W	_	0.10	-	0.004		




Dim.	Millimeter		Inches	
Dim.	min	max	min	max
Α	4.83	5.21	0.190	0.205
A1	2.29	2.54	0.090	0.100
A2	1.91	2.16	0.075	0.085
b	1.14	1.40	0.045	0.055
b2	1.91	2.20	0.075	0.087
b4	2.92	3.24	0.115	0.128
C	0.61	0.83	0.024	0.033
D	20.80	21.34	0.819	0.840
D1	15.75	16.26	0.620	0.640
D2	1.65	2.15	0.065	0.085
D3	20.30	20.70	0.799	0.815
Е	15.75	16.13	0.620	0.635
E1	13.21	13.72	0.520	0.540
е	10.90	BSC	0.430 BSC	
L	19.81	20.60	0.780	0.811
L1	3.81	4.38	0.150	0.172
Q	5.59	6.20	0.220	0.244
R	4.25	5.50	0.167	0.217
W	-	0.10	-	0.004




Dim.	Millimeter		Inches	
	min	max	min	max
Α	4.70	5.30	0.185	0.209
A1	2.21	2.59	0.087	0.102
A2	1.50	2.49	0.059	0.098
b	0.99	1.40	0.039	0.055
b2	1.65	2.39	0.065	0.094
b4	2.59	3.43	0.102	0.135
С	0.38	0.89	0.015	0.035
D	20.79	21.45	0.819	0.844
Е	15.49	16.24	0.610	0.639
E2	4.31	5.48	0.170	0.216
е	5.46	BSC	0.215 BSC	
L	19.80	20.30	0.780	0.799
L1	-	4.49	-	0.177
ØΡ	3.55	3.65	0.140	0.144
Q	5.38	6.19	0.212	0.244








Dimensions in mm and inches (1 mm = 0.0394")




	07-8'	A2}


Dim.	Millimeter		Inches	
	min	max	min	max
Α	4.90	5.10	0.193	0.201
A1	2.70	2.90	0.106	0.114
A2	0.02	0.25	0.001	0.100
b	1.15	1.45	0.045	0.057
С	0.40	0.65	0.016	0.026
C 2	1.45	1.60	0.057	0.063
D	13.80	14.00	0.543	0.551
D1	11.80	12.10	0.465	0.476
D2	7.50	7.80	0.295	0.307
D3	2.90	3.20	0.114	0.126
Е	15.85	16.05	0.624	0.632
E1	13.30	13.60	0.524	0.535
е	5.45	BSC	0.215 BSC	
Н	18.70	19.10	0.736	0.752
L	1.70	2.00	0.067	0.079
L2	1.00	1.15	0.039	0.045
L3	0.25 BSC		0.010	BSC
L4	3.80	4.10	0.150	0.161




Dim.	Millin	neter	Incl	nes
Diiii.	min	max	min	max
Α	4.82	5.13	0.190	0.202
A1	2.54	2.89	0.100	0.114
A2	2.00	2.10	0.079	0.083
b	1.12	1.42	0.044	0.056
b2	2.90	3.09	0.114	0.122
С	0.53	0.83	0.021	0.033
D	25.91	26.16	1.020	1.030
Е	19.81	19.96	0.780	0.786
е	5.45 BSC		0.215 BSC	
J	0.00	0.25	0.000	0.010
K	0.00	0.25	0.000	0.010
L	20.32	20.83	0.800	0.820
L1	2.29	2.59	0.090	0.102
Р	3.17	2.66	0.125	0.144
Q	6.07	6.27	0.239	0.247
Q1	8.38	8.69	0.330	0.342
R	3.81	4.32	0.150	0.170
R1	1.78	2.29	0.070	0.090
S	6.04	6.30	0.238	0.248
Т	1.57	1.83	0.062	0.072



Dim.	Millimeter		Inches	
ווווט.	min	max	min	max
Α	4.70	5.31	0.185	0.209
A1	2.59	3.00	0.102	0.118
b	0.94	1.40	0.037	0.055
b1	2.21	2.59	0.087	0.102
b2	2.79	3.20	0.110	0.126
С	0.43	0.74	0.017	0.029
D	25.58	26.59	1.007	1.047
Е	19.30	20.29	0.760	0.799
е	5.45	BSC	0.215 BSC	
L	19.79	21.39	0.779	0.842
L1	2.21	2.59	0.087	0.102
Q	6.10	6.50	0.240	0.256
Q1	8.38	8.79	0.330	0.346
ØR	3.94	4.75	0.155	0.187
ØR1	2.16	2.36	0.085	0.093




Dim.	Millimeter		Inches	
Diiii.	min	max	min	max
Α	4.83	5.21	0.190	0.205
A1	2.59	3.00	0.102	0.118
A2	1.17	1.40	0.046	0.055
b	1.14	1.40	0.045	0.055
b1	1.60	1.83	0.063	0.072
b2	2.54	2.79	0.100	0.110
b3	1.47	1.73	0.058	0.068
С	0.51	0.74	0.020	0.029
D	25.91	26.42	1.020	1.040
E	19.56	20.29	0.770	0.799
е	3.81	BSC	0.150 BSC	
L	19.81	21.83	0.780	0.820
L1	2.03	2.59	0.080	0.102
Q	5.33	5.97	0.210	0.235
Q1	12.45	13.03	0.490	0.513
R	3.81	4.57	0.150	0.180
R1	2.54	3.30	0.100	0.130
S	16.97	17.53	0.668	0.690
Т	20.34	20.85	0.801	0.821
U	1.65	2.03	0.065	0.080



X022 ISOPLUS264™

c) 5 pin


Dim.	Millin	neter	Inc	hes
Diiii.	min	max	min	max
Α	4.83	5.21	0.190	0.205
A1	2.59	3.00	0.102	0.118
A2	1.17	1.40	0.046	0.055
b	1.14	1.40	0.045	0.055
b1	1.60	1.83	0.063	0.072
b2	2.54	2.79	0.100	0.110
b3	1.47	1.73	0.058	0.068
С	0.51	0.74	0.020	0.029
D	25.91	26.42	1.020	1.040
Е	19.56	20.29	0.770	0.799
е	3.81	BSC	0.150 BSC	
L	19.81	21.83	0.780	0.820
L1	2.03	2.59	0.080	0.102
Q	5.33	5.97	0.210	0.235
Q1	12.45	13.03	0.490	0.513
R	3.81	4.57	0.150	0.180
R1	2.54	3.30	0.100	0.130
S	16.97	17.53	0.668	0.690
Т	20.34	20.85	0.801	0.821
U	1.65	2.03	0.065	0.080




Dim.	Millin	neter	Inc	nes
Diiii.	min	max	min	max
Α	4.83	5.21	0.190	0.205
A1	2.59	3.00	0.102	0.118
A2	1.17	1.40	0.046	0.055
b	1.14	1.40	0.045	0.055
b1	1.60	1.83	0.063	0.072
b2	2.54	2.79	0.100	0.110
b3	1.47	1.73	0.058	0.068
С	0.51	0.74	0.020	0.029
D	25.91	26.42	1.020	1.040
Е	19.56	20.29	0.770	0.799
е	3.81	BSC	0.150 BSC	
L	19.81	21.83	0.780	0.820
L1	2.03	2.59	0.080	0.102
Р	3.30	3.68	0.130	0.145
Q	5.33	5.97	0.210	0.235
Q1	12.45	13.03	0.490	0.513
Q2	5.96	6.48	0.235	0.255
R	3.81	4.57	0.150	0.180
R1	2.54	3.30	0.100	0.130
S	16.97	17.53	0.668	0.690
Т	11.94	12.45	0.470	0.490
U	9.91	10.41	0.390	0.410




Dimensions in mm and inches (1 mm = 0.0394")




Dim.	Millimeter		Inches	
ווווט.	min	max	min	max
Α	4.83	5.21	0.190	0.205
A1	2.59	3.00	0.102	0.118
A2	1.17	2.16	0.046	0.085
b	1.14	1.40	0.045	0.055
b2	1.47	1.73	0.058	0.068
b4	2.54	2.79	0.100	0.110
С	0.51	0.74	0.020	0.029
D	20.80	21.34	0.819	0.840
D1	14.99	15.75	0.590	0.620
D2	1.65	2.03	0.065	0.080
D3	20.30	20.70	0.799	0.815
Е	19.56	20.29	0.770	0.799
E1	16.76	17.53	0.660	0.690
е	3.81	BSC	0.150	BSC
L	19.81	21.34	0.780	0.840
L1	2.11	2.59	0.083	0.102
Q	5.33	6.20	0.210	0.244
R	2.54	4.57	0.100	0.180
W		0.10	-	0.004




Dim.	Millimeter		Inches	
Dim.	min	max	min	max
Α	4.83	5.21	0.190	0.205
A1	2.59	3.00	0.102	0.118
A2	1.17	2.16	0.046	0.085
b	1.14	1.40	0.045	0.055
b2	1.47	1.73	0.058	0.068
b4	2.54	2.79	0.100	0.110
С	0.51	0.74	0.020	0.029
D	20.80	21.34	0.819	0.840
D1	14.99	15.75	0.590	0.620
D2	1.65	2.03	0.065	0.080
D3	20.30	20.70	0.799	0.815
Е	19.56	20.29	0.770	0.799
E1	16.76	17.53	0.660	0.690
е	7.62	BSC	0.300 BSC	
L	19.81	21.34	0.780	0.840
L1	2.11	2.59	0.083	0.102
Q	5.33	6.20	0.210	0.244
R	2.54	4.57	0.100	0.180
W	-	0.10	-	0.004




	depending on assembly line				
Dim.	Millin	neter	Inc	hes	
Diiii.	min	max	min	max	
Α	4.83	5.21	0.190	0.205	
A1	2.59	3.00	0.102	0.118	
A2	1.17	2.16	0.046	0.085	
b	1.14	1.40	0.045	0.055	
b2	1.47	1.73	0.058	0.068	
b4*	2.54	2.79	0.100	0.110	
С	0.51	0.74	0.020	0.029	
D	20.80	21.34	0.819	0.840	
D1	14.99	15.75	0.590	0.620	
D2	1.65	2.03	0.065	0.080	
D3	20.30	20.70	0.799	0.815	
Е	19.56	20.29	0.770	0.799	
E1	16.76	17.53	0.660	0.690	
е	3.81	BSC	0.150 BSC		
e1	11.43	BSC	0.450	BSC	
L	19.81	21.34	0.780	0.840	
L1	2.11	2.59	0.083	0.102	
Q	5.33	6.20	0.210	0.244	
R	2.54	4.57	0.100	0.180	
W	-	0.10	-	0.004	



Dim.	Millir	neter	Inches		
Dim.	min	max	min	max	
Α	4.83	5.21	0.190	0.205	
A1	2.59	3.00	0.102	0.118	
A2	1.17	2.16	0.046	0.085	
b	1.14	1.40	0.045	0.055	
b2	1.47	1.73	0.058	0.068	
С	0.51	0.74	0.020	0.029	
D	20.80	21.34	0.819	0.840	
D1	14.99	15.75	0.590	0.620	
D2	1.65	2.03	0.065	0.080	
D3	20.30	20.70	0.799	0.815	
Е	19.56	20.29	0.770	0.799	
E1	16.76	17.53	0.660	0.690	
е	3.81	BSC	0.150	BSC	
┙	19.81	21.34	0.780	0.840	
L1	2.11	2.59	0.083	0.102	
Q	5.33	6.20	0.210	0.244	
R	2.54	4.57	0.100	0.180	
W	-	0.10	-	0.004	




Dim.	Millin	neter	Inc	hes
Dim.	min	max	min	max
Α	4.83	5.21	0.190	0.205
A1	2.59	3.00	0.102	0.118
A2	1.17	2.16	0.046	0.085
b	1.14	1.40	0.045	0.055
b2	1.47	1.73	0.058	0.068
С	0.51	0.74	0.020	0.029
D	20.80	21.34	0.819	0.840
D1	14.99	15.75	0.590	0.620
D2	1.65	2.03	0.065	0.080
D3	20.30	20.70	0.799	0.815
Е	19.56	20.29	0.770	0.799
E1	16.76	17.53	0.660	0.690
е	15.24	BSC	0.600	BSC
L	19.81	21.34	0.780	0.840
L1	2.11	2.59	0.083	0.102
Q	5.33	6.20	0.210	0.244
R	2.54	4.57	0.100	0.180
W	-	0.10	-	0.004




Weight = 7 g

Dim.	Millimeter		Inches	
	min	max	min	max
Α	29.70	30.30	1.170	1.194
В	19.70	20.30	0.776	0.800
С	17.00	18.00	0.670	0.709
D	4.70	4.90	0.185	0.193
Е	10.80	11.20	0.426	0.441
F	2.30	2.70	0.091	0.106
G	3.10	3.40	0.122	0.134
Н	3.40	3.80	0.134	0.150
- 1	4.40	4.80	0.173	0.189
J	2.50	2.90	0.099	0.114
K	0.60	0.80	0.024	0.032
L	2.00	2.40	0.079	0.095
М	0.90	1.10	0.035	0.043
N	9.80	10.20	0.386	0.402
0	7.30	7.70	0.288	0.303
Р	3.80	4.20	0.150	0.165
Q	(3.0) x 45°		(0.118) x 45°	
ØR	3.1	3.4	0.122	0.134













Weight = 8.5 g

Dimensions in mm and inches (1 mm = 0.0394")



Dim.	Millimeter		Inches	
	min	max	min	max
Α	5.30	5.70	0.209	0.224
A1	3.90	4.10	0.154	0.161
A2	1.40	1.60	0.055	0.063
b	0.90	1.15	0.035	0.045
С	0.45	0.65	0.018	0.026
D	24.80	25.25	0.976	0.994
Е	22.80	23.25	0.898	0.915
E1	13.80	14.20	0.543	0.559
е	2.00	BSC	0.079	BSC
e1	8.00	BSC	0.315	BSC
Н	32.30	33.30	1.272	1.311
L	4.60	5.30	0.181	0.209
L1	1.30	1.70	0.051	0.067
L2	0.00	0.15	0.000	0.006
S	18.85	20.12	0.742	0.792
S1	1.45	2.08	0.057	0.082
Т	20.90	22.17	0.823	0.873
T1	1.42	2.03	0.056	0.080
а	4°	-	4°	-


X031b SMPD-X




INCHES MILLIMETERS				
MYZ	INCHES		MILLIMETERS	
	MIN	MAX	MIN	MAX
Α	.209	.224	5.30	5.70
A1	.154	.161	3.90	4.10
A2	.055	.063	1.40	1.60
Ь	.035	.045	0.90	1.15
С	.018	.026	0.45	0.65
D	.976	.994	24.80	25.25
E	.898	.915	22.80	23.25
E1	.543	.559	13.80	14.20
е	.079 BSC		2.00 BSC	
e1	.394 BSC		10.00 BSC	
e2	.315 BSC		8'00 B2C	
Н	1.272	1.311	32,30	33,30
L	.181	.209	4.60	5,30
L1	.051	.067	1.30	1.70
L2	.000	.006	0.00	0.15
S	.742	.792	18.85	20.12
S1	.057	.082	1.45	2.08
T	.823	.873	20.90	22.17
T1	.069	.089	1.75	2,25
X	0	4°	0	4°

- Bottom heatsink meets 2.6KV AC isolation to the other pins.
 All leads are matte pure tin plated.








































































l → 6B →				
Dim.	Millimeter		Inches	
	min	max	min	max
Α	3.56	4.57	0.140	0.180
A1	0.38	1.02	0.015	0.040
A2	3.18	3.68	0.125	0.145
b	0.38	0.51	0.015	0.020
b2	1.40	1.65	0.055	0.065
b3	0.89	1.14	0.035	0.045
С	0.23	0.30	0.009	0.012
D	9.02	10.16	0.355	0.400
D1	0.25	1.02	0.010	0.040
E	7.62	8.26	0.300	0.325
E1	6.10	6.86	0.240	0.270
е	2.54 BSC		0.100 BSC	
eA	7.62 BSC		0.300 BSC	
eВ	7.62	10.92	0.300	0.430
L	3.05	3.56	0.120	0.140



Dim.	Millimeter		Inches	
	min	max	min	max
Α	1.35	1.75	0.053	0.069
A1	0.10	0.25	0.004	0.010
В	0.33	0.51	0.013	0.020
С	0.19	0.25	0.007	0.010
D*	4.80	5.00	0.189	0.197
E*	3.80	4.00	0.150	0.158
E1	6.10	6.86	0.240	0.270
F	1.27 BSC		0.050 BSC	
Н	5.8	6.2	0.229	0.244
J	0.25	0.50	0.010	0.020
K	0°	8°	0°	8°
L	0.40	1.27	0.016	0.050
* do r	* do not include Mold protrusions			





Application Notes Highlights further information and downloads see www.ixys.com



Power Fact	tor Correction
IXAN0001	3-Phase PFC using Vienna Rectifier Approach and Modular Construction for Improved Overall Performance, Efficiency and Reliability
IXAN0002	Single and Three-Phase Rectifiers with Active Power Factor Correction for Enhanced Mains Power Quality
IXAN0003	Rectifiers with Power Factor Correction
IXAN0004	Design and Experimental Investigation of a Three-Phase, High Power Density, High Efficiency, Unity Power Factor PWM (VIENNA) Rectifier Employing a Novel Integrated Power Semiconductor Module
IXAN0005	Status of the Techniques of Three-Phase Rectifier Systems with Low Effects on the Mains
MOSFETs	and IGBTs Drivers
IXAN0012	MOSFET/IGBT Drivers - Theory and Applications
IXAN0011	Driving Your MOSFETs Wild to Obtain Greater Efficiencies, Power Densities and Lower Overall Cost
BIMOSFET	's Applications
IXAN0013	Capacitor Charge/Discharge Circuits, utilizing High Voltage IGBTs and ZCS Resonant Mode Techniques
IXAN0014	Comparative Performance of BiMOSFETs in Fly-back Converter Circuits
IXAN0015	Use of BiMOSFETs in Modern Radar Transmitters
IXAN0016	IXBH40N160 BiMOSFET Developed for High Voltage and High Frequency Applications
IXAN0017	New 1600V BiMOSFET Transistors Open Up New Applications
Automotive	e Applications
IXAN0018	A High Current Dual Inline Packaged Trench MOSFET Three Phase Full Bridge as Contribution to Automotive System Integration
IXAN0019	High Power TrenchMOSFETs Solutions in Automotive Designs
IXAN0020	Power Electronic Supply for Automotive Starter Generator
IXAN0021	New Trench Power MOSFETs in Isolated Packages
Isolation Te	echniques, Mounting, Soldering and Cooling
IXAN0071	The SMPD Package and its Mounting Instructions
IXAN0022	Capitalizing on the Advantages of ISOPLUS Products
IXAN0023	General Mounting Instructions
IXAN0025	ISOPLUS-The Revolution in Discrete Isolation Technique
IXAN0026	Combining the Features of Modules and Discretes in a New Power Semiconductor Packages
IXAN0028	The Revolution in Discrete Isolation Technique
IXAN0030	Surface Mount Soldering Recommendations for TO-263 and TO-268 case styles
IXAN0031	New ISOPLU247 Power Package Features 2500V Internal Isolation Revolutionary Approach Improves Thermal Conductance and Reliability
Power Mod	lules
IXAN0034	Recommended Use of the Integrated NTC Thermistor Temperature Sensor in IXYS Power Modules
IXAN0035	Mounting Instructions for _A7, _E7, _A8 and _E8 Module Series
IXAN0036	Investigations on Electromagnetic Compatibility of Power Semiconductor Modules Integrated in a Module
IXAN0037	Power Cycle Capability of solder contact DCB-Modules
FREDs and	I Schottky Diodes
IXAN0042	Is the Lowest Forward Voltage Drop Schottky Diode Always the Best Choice?
IXAN0043	Input Rectifiers with Semifast Diodes for DC link.
IXAN0044	Characteristics and Applications of Fast Recovery Epitaxial Diodes.
IXAN0060	Optimized Ultra Fast Diodes for Switching Applications
Power MOS	SFETS
IXAN0057	Series Operation of MOSFET and IGBT Switches
IXAN0061	Power MOSFET Basics
IXAN0062	IXYS Power MOSFET Products
IXAN0063	Application note on Depletion-mode
IXAN0064	IXYS P-Channel MOSFET
IXAN0065	IXYS Power MOSFET Datasheet Parameters Definition
IXAN0068	Linear Power MOSFETS Basic and Application
IXAN0069	Synchronous DC to DC Converter Design
IGBTs	
IXAN0063	IGBTs
IXAN0070	Drive with the IXYS XPT IGBT
IXAN0072	Discrete 600V GenX3 XPT IGBTs
	2.55.55 557 65.76 7. 162.15