

Two-column maintenance note

1. Finding

The north pump failed its inspection on 6 May 2024. No outage was recorded.

2. Action

Replace the seal before 30 June 2024; then verify pressure at 12 bar.

Sidebar: 12 bar is a planned check, not a measured result.