

VNCT LOTUS VILLAS SITE PICS

22-02-16



Cluster C: Outer Plastering Work in Progress

VNCT LOTUS VILLAS SITE PICS

22-02-16



Cluster D: Outer Plastering Work in Progress

VNCT LOTUS VILLAS SITE PICS

22-02-16



Cluster H: Plinth Beam Bar Bending & RCC Work in Progress

VNCT LOTUS VILLAS SITE PICS

22-02-16



Cluster J: Plinth Beam Bar Bending Work in Progress

VNCT LOTUS VILLAS SITE PICS

22-02-16



Cluster N: Outer Wall Plastering & Painting Work in Progress

VNCT LOTUS VILLAS SITE PICS

22-02-16



Cluster O: Outer Wall Plastering & Painting Work in Progress

VNCT LOTUS VILLAS SITE PICS

22-02-16



Cluster P: Outer Wall Plastering Work in Progress

VNCT LOTUS VILLAS SITE PICS

22-02-16



Cluster Q: Outer Wall Plastering Work in Progress

VNCT LOTUS VILLAS SITE PICS

22-02-16



Cluster R: Earth Work Excavation Work in Progress

VNCT LOTUS VILLAS SITE PICS

22-02-16



Cluster S: Earth Work Excavation Work in Progress

VNCT LOTUS VILLAS SITE PICS

22-02-16



Cluster U: Column Box RCC Work in Progress

VNCT LOTUS VILLAS SITE PICS

22-02-16



Cluster U: Basement Filling Work in Progress

VNCT LOTUS VILLAS SITE PICS

22-02-16



Cluster V: Plinth Beam Bar Bending & Shuttering Work in Progress

VNCT LOTUS VILLAS SITE PICS

22-02-16



Cluster W: Earth Work Excavation Work in Progress