Reliability Index vs. Gumbel Mean of SWE Reliability target = 3.8Reliability Index **Gumbel Mean of SWE**