Number of observations before 1950: 10


Number of observations after 1950: 0

Mean of covariance norms: 0.0046568

Variance of covariance norms: 2.6e-06

minimum: 0.0026593


maximum: 0.0076379 - note: all rounded to 7 significant digits



Number of observations before 1950: 20 Number of observations after 1950: 0 Mean of covariance norms: 0.0079573 Variance of covariance norms: 2.04e-05

minimum: 0.002976

maximum: 0.017019 - note: all rounded to 7 significant digits



Number of observations before 1950: 40


Number of observations after 1950: 0

Mean of covariance norms: 0.0060539

Variance of covariance norms: 6.3e-06

minimum: 0.0019767


maximum: 0.0129253 - note: all rounded to 7 significant digits



Number of observations before 1950: 80 Number of observations after 1950: 0 Mean of covariance norms: 0.0067466 Variance of covariance norms: 8.8e-06

minimum: 0.0014256

maximum: 0.0159673 - note: all rounded to 7 significant digits



Number of observations before 1950: 200

Number of observations after 1950: 0

Mean of covariance norms: 0.0076255

Variance of covariance norms: 9.8e-06

minimum: 0.0014024

maximum: 0.0191817 - note: all rounded to 7 significant digits

