## MECH366 Modeling of Mechatronic Systems Exercise solutions for ODE solutions

1. Inverse Laplace transform:  $f(t) = \mathcal{L}^{-1} \{F(s)\}$ 

(a) 
$$F(s) = \frac{5}{s(s+1)(s+2)} = \frac{5/2}{s} - \frac{5}{s+1} + \frac{5/2}{s+2}$$
  

$$\Rightarrow f(t) = \frac{5}{2} - 5e^{-t} + \frac{5}{2}e^{-2t}$$

Final value theorem:

$$\lim_{t \to \infty} f(t) = \lim_{s \to 0} sF(s) = \frac{5}{2}$$

(b) 
$$F(s) = \frac{1}{s^2(s+1)} = -\frac{1}{s} + \frac{1}{s^2} + \frac{1}{s+1}$$
  

$$\Rightarrow f(t) = -1 + t + e^{-t}$$

Final value theorem does not apply in this case, since sF(s) has a pole (i.e., denominator root) at the origin. In fact, f(t) goes to infinity as t does.

(c) 
$$F(s) = \frac{2s+1}{s^2+2s+10} = \frac{2(s+1)}{(s+1)^2+3^2} - \frac{1}{3} \cdot \frac{3}{(s+1)^2+3^2}$$
  

$$\Rightarrow f(t) = 2e^{-t}\cos 3t - \frac{1}{3}e^{-t}\sin 3t$$

Final value theorem:

$$\lim_{t \to \infty} f(t) = \lim_{s \to 0} sF(s) = 0$$

(d) 
$$F(s) = \frac{s - 30}{s(s^2 + 4s + 29)} = -\frac{30}{29} \cdot \frac{1}{s} + \frac{1}{29} \cdot \frac{30s + 149}{(s + 2)^2 + 5^2} = -\frac{30}{29} \cdot \frac{1}{s} + \frac{1}{29} \cdot \frac{30(s + 2) + 89}{(s + 2)^2 + 5^2}$$

$$\Rightarrow f(t) = \frac{30}{29} \left( -1 + e^{-2t} \cos 5t \right) + \frac{89}{29 \cdot 5} e^{-2t} \sin 5t$$

Final value theorem:

$$\lim_{t \to \infty} f(t) = \lim_{s \to 0} sF(s) = -\frac{30}{29}$$

2. 
$$F(s) = \frac{s+5}{s(s^2+4s+13)} = \frac{5}{13} \cdot \frac{1}{s} - \frac{1}{13} \cdot \frac{5s+7}{(s+2)^2+3^2}.$$
$$\Rightarrow f(t) = \frac{5}{13} \left(1 - e^{-2t} \cos 3t\right) + \frac{1}{13} e^{-2t} \sin 3t$$

3. Laplace transform

$$\frac{d^2x(t)}{dt^2} + 5\frac{dx(t)}{dt} + 4x(t) = 10u(t)$$

$$\Rightarrow (s^2X(s) - sx(0) - x'(0)) + 5(sX(s) - x(0)) + 4X(s) = \frac{10}{s}$$

$$\Rightarrow X(s) = \frac{1}{s^2 + 5s + 4} \left(\frac{10}{s} + (s+5)x(0) + x'(0)\right)$$

(a) x(0) = x'(0) = 0.

$$X(s) = \frac{1}{s^2 + 5s + 4} \cdot \frac{10}{s} = \frac{5}{2} \cdot \frac{1}{s} - \frac{10}{3} \cdot \frac{1}{s+1} + \frac{5}{6} \cdot \frac{1}{s+4}$$
$$\Rightarrow x(t) = \frac{5}{2} - \frac{10}{3}e^{-t} + \frac{5}{6}e^{-4t}$$

(b) x(0) = x'(0) = 1.

$$X(s) = \frac{1}{s^2 + 5s + 4} \cdot \frac{s^2 + 6s + 10}{s} = \frac{5}{2} \cdot \frac{1}{s} - \frac{5}{3} \cdot \frac{1}{s + 1} + \frac{1}{6} \cdot \frac{1}{s + 4}$$
$$\Rightarrow x(t) = \frac{5}{2} - \frac{5}{3}e^{-t} + \frac{1}{6}e^{-4t}$$

4. Laplace transform

$$\frac{d^2x(t)}{dt^2} + 2\frac{dx(t)}{dt} + x(t) = 5u(t)$$

$$\Rightarrow (s^2X(s) - sx(0) - x'(0)) + 2(sX(s) - x(0)) + X(s) = \frac{5}{s}$$

$$\Rightarrow X(s) = \frac{1}{(s+1)^2} \left(\frac{5}{s} + (s+2)x(0) + x'(0)\right)$$

(a) x(0) = x'(0) = 0.

$$X(s) = \frac{1}{(s+1)^2} \cdot \frac{5}{s} = 5 \cdot \frac{1}{s} - 5 \cdot \frac{1}{s+1} - 5 \cdot \frac{1}{(s+1)^2}$$
  
$$\Rightarrow x(t) = 5(1 - e^{-t} - te^{-t})$$

(b) x(0) = 0, x'(0) = 2.

$$X(s) = \frac{1}{(s+1)^2} \cdot \frac{2s+5}{s} = 5 \cdot \frac{1}{s} - 5 \cdot \frac{1}{s+1} - 3 \cdot \frac{1}{(s+1)^2}$$
  

$$\Rightarrow x(t) = 5(1 - e^{-t}) - 3te^{-t}$$

5. (a) 
$$c''(t) + 10c'(t) + 60c(t) = 60r(t), c(0) = c'(0) = 0$$

(b) 
$$c'''(t) + 4c''(t) + 8c'(t) + 20c(t) = 3r'(t) + 20r(t)$$
,  $c(0) = c'(0) = c''(0) = r(0) = 0$ 

(c) 
$$c''(t) = r'(t) + r(t)$$
,  $c(0) = c'(0) = r(0) = 0$ 

(d) 
$$c''(t) + 5c'(t) + 32c(t) = 7r(t - 0.2), c(0) = c'(0) = 0$$