SECTION II. QUALITY AND MONITORING

Examples of quality check and inspection

Milk cap

Car body inspection featuring multi-sensor CMM (Coordinate Measure Machine)

- The principles of statistical process control
 - o Process Capability Index Part 1
 - o Process Capability Index Part 2
 - o Process Capability Index Part 3
- 6σ
- o What is 6 Sigma?
- o Introduction to Six Sigma