Trinasolar		平均功率 Average Power		组件色系码 Color Code		
					9	
NO	SN	NO	s	N	NO	SN
1	K03221100940991	2	K032211	<b>                                    </b>	3	K03221100940986
4	K03221100940462	5	K032211	00940142	6	K03221100940996
7		8	K032211	00940558	9	K03221100940115
10	K03221100940769	11	K032211	00940984	12	K03221100940997
13	K03221100940912	14	K0322110	00940440	15	K03221100940913
16	K03221100940849	17	K0322110	00941554		
		18	K0322110	00940042	19	K03221100940987
20	K03221100940453	21	K0322110	00940071	22	
23	K03221100940035	24		00940510	25	K03221100940838
26	K03221100940844	27	K0322110	00941376	28	K03221100941412
29	K03221100940960	3 <mark>7</mark>		00940962	31	K03221100940891
32	K03221100940842	33	K03221100940525		34	K03221100940508
	·				-	
		,				·
托盘号/Pallet Number				产品编码Product Name		
	K03221122003346A01	049B	TSM-430DE09R.08			
	PASS	)	N/A			

建议:对于组件颜色有要求的客户,建议不同色系组件避免安装在同一阵列或屋顶中。组件颜色区分对组件性能没有影响。

Suggestion: If color uniformity of the array is desired, it is recommended that only modules with the same color code be installed. There will be no impact to performance if modules with different color codes are installed together.