

## **Halliburton N-Seal**

INGREDIENTS	CAS NO	%	8HR OEL
blast furnace slag	65996-69-2	>60	-

UN No: Not Applicable
Hazchem Code: Not Applicable
DG Class: Not Applicable
Subsidiary Risk: Not Applicable
Packing Group: Not Applicable
Poisons Schedule: Not Applicable



#### NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ **3**: High
- ▶ 4: Extreme

## **HEALTH HAZARD INFORMATION**





Acute Health Effects: Causes burns.

Risk of serious damage to eyes.

## PRECAUTIONS FOR USE













Appropriate engineering controls:	General Exhaust Ventilation adequate.
Glasses:	Consider full face-shield.
Gloves:	Neoprene. Leather Gloves.
Respirator:	Type AX-P Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)
Storage and Transportation:	Store in cool, dry, protected area. Keep locked up. Keep out of reach of children. Keep away from living quarters.
Fire/Explosion Hazard:	Toxic smoke/fumes in a fire.

#### **PROPERTIES**







Solid. Does

Does not mix with water. Sinks in water. Alkaline.Combustible.

## **EMERGENCY**











<b>FIRST</b>	<b>AID</b>
--------------	------------

Swallowed:	Give water (if conscious). URGENT MEDICAL ATTENTION.
Eye:	Wash with running water (15 mins). Medical attention.
Skin:	Flood body with water. Remove contaminated clothing. Wash with water
Inhaled:	Fresh air. Rest, keep warm. If breathing shallow, give oxygen. Medical attention.
Advice To Doctor:	Treat symptomatically. Supportive care. Irrigate eyes with saline. Supportive care.
Fire Fighting:	Foam.
	Eliminate ignition sources.

Avoid dust.

Spills and Disposal:

Sweep shovel to safe place.

This material and its container must be disposed of in a cofe way.

in a safe way.

To clean the floor and all objects contaminated by this material, use water and detergent.

# SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS







Explosive Radioactive Oxidizing x x x x