

METHANOL

INGREDIENTS	CAS NO	%	8HR OEL
methanol	67-56-1	>98	262 mg/m3



UN No: 1230 Hazchem Code: •2WE DG Class: 3 Subsidiary Risk: 6.1 Packing Group: II Poisons Schedule: S6



NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

PROPERTIES







Liquid. Mixes with water. Highly flammable.

EMERGENCY













HEALTH HAZARD INFORMATION







Toxic by inhalation. Toxic in contact with skin.

Acute Health Effects: Toxic if swallowed.

Toxic: Danger of very serious irreversible effects through inhalation, in contact with skin and if

swallowed.

PRECAUTIONS FOR USE



















Appropriate engineering controls:

Local Exhaust Ventilation recommended.

Glasses:

Consider chemical goggles.

Gloves:

1.BUTYL 2.BUTYL/NEOPRENE 3.PVC

Respirator:

Storage and

Transportation:

Type AX Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)

Restrictions on Storage apply. Refer to Full Report. Take precautionary measures against static discharges. Dispose of this material and its

container at hazardous or special waste collection point. Keep locked up. Keep out of reach of children. Keep away from living quarters. Keep container in a well ventilated place. Keep away

from food, drink and animal feeding stuffs. Keep away from sources of ignition. No smoking.

Fire/Explosion Hazard:

HIGHLY FLAMMABLE. Vapours/gas heavier than air. Toxic smoke/fumes in a fire. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. In case of fire and/or explosion, DO NOT BREATHE FUMES.

FIRST AID

If more than 15 mins from Doctor, INDUCE Swallowed: VOMITING (if conscious). Do NOT give milk or oil.

Do NOT give alcohol.

Wash with running water (15 mins). Medical Eye:

attention.

Wipe-off with clean/dry cloth. Remove Skin:

contaminated clothing. Wash with water & soap.

MEDICAL ATTENTION.

Fresh air. Rest, keep warm. If breath shallow, give Inhaled:

oxygen. Medical attention.

Advice To Decontaminate with ipecac or lavage. Ethanol

therapy.

Doctor:

Spills and

Disposal:

Keep containers cool. Water spray/ fog. Foam -Fire Fighting:

alcohol type.

Spilled liquid has low boiling temperature and evaporates quickly. Eliminate ignition sources. Consider evacuation. Prevent from entering drains. Contain spillage by any means. Control vapour with water spray/ fog. Absorb with dry agent. Stop leak if safe to do so. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection

point. This material and its container must be disposed of in a safe way. To clean the floor and all objects contaminated by this material, use water.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS











Flammable Explosive х

Toxic

Radioactive Oxidizing

x x x

- Must not be stored together