

Schlumberger Sludge And Emulsion Preventer W60

INGREDIENTS	CAS NO	%	8HR OEL
ethylene glycol monobutyl ether	111-76-2	5-10	96.9 mg/m3
ethylene glycol	107-21-1	1-5	10 mg/m3
isopropanol	67-63-0	10-30	983 mg/m3
dodecylbenzenesulfonic acid	27176-87-0	30-60	-



UN No: 2920 Hazchem Code: •3W DG Class: 8 Subsidiary Risk: 3 Packing Group: II Poisons Schedule: S6

NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

PROPERTIES









Liquid. Mixes with water. Corrosive. Acid.R10R19

EMERGENCY









Acute Health Effects:

Causes severe burns.

Risk of serious damage to eyes.

Vapours may cause drowsiness and dizziness.

Chronic **Health Effects:** May cause CANCER by inhalation.

* - limited evidence

PRECAUTIONS FOR USE







Loca

HEALTH HAZARD INFORMATION









	(00)	46	×
al Exhaust Ve	ntilation re	ecommend	ed.

Glasses: Gloves:

Appropriate

engineering

controls:

Consider full face-shield.

1.PE/EVAL/PE 2.NEOPRENE 3.PVC

Respirator:

Type AB-P Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)

Storage and Transportation:

Restrictions on Storage apply. Refer to Full Report. Dispose of this material and its container at hazardous or special waste collection point. Keep locked up. Keep out of reach of children. Keep away from living quarters. Handle and open container with care.

Fire/Explosion Hazard:

HIGHLY FLAMMABLE. Toxic smoke/fumes in a fire. Attacks metals to liberate hydrogen. Dispose of this material and its container at hazardous or special waste collection point.

Environment:

Toxic to aquatic organisms. Use appropriate container to avoid environmental contamination.

FIRST AID

Give water (if conscious). URGENT MEDICAL Swallowed: ATTENTION. Wash with running water (15 mins). Medical Eye: attention.

> Flood body with water. Remove contaminated Skin: clothing. Wash with water

Fresh air. Rest, keep warm. If breath shallow, give Inhaled:

oxygen. Medical attention.

Advice To Doctor:

Retract eyelids - irrigate 30 mins. Retract eyelids/ Irrigate 30 mins. Severe exposure indicated by respiratory distress/hypotension Managements is essentially supportive.

Airway problems - 100% O2. Treat burns as thermal.

Fire Fighting:

Keep containers cool. Water spray/ fog. Foam alcohol type.

Spills and Disposal:

Eliminate ignition sources. Pollutant. Prevent from entering drains. Contain spillage by any means. Absorb with dry agent. Neutralize with soda ash/ lime. Stop leak if safe to do so. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be disposed of in a safe way. To clean the floor and all objects contaminated by this material, use water.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS









x x

Toxic

Radioactive Oxidizing х Х

- Must not be stored together