

## **Hempel'S Coal Tar Epoxy Mastic 35679**

INGREDIENTS	CAS NO	%	8HR OEL
xylene	1330-20-7	5-<10	350 mg/m3
methyl isobutyl ketone	108-10-1	3-<5	205 mg/m3
ethylbenzene	100-41-4	1-<3	434 mg/m3
distillates, coal tar, upper	65996-91-0	10-<25	-



UN No: 1263 Hazchem Code: •3Y DG Class: 3

Subsidiary Risk: Not Applicable

Packing Group: III Poisons Schedule: \$5



### NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

### **HEALTH HAZARD INFORMATION**









**Acute Health** Effects: Harmful by inhalation. Irritating to eyes.

Irritating to skin. Vapours may cause drowsiness and dizziness.

Chronic **Health Effects:**  May cause CANCER.

\* - limited evidence

# PRECAUTIONS FOR USE













٠	
	Appropriate
	engineering

Local Exhaust Ventilation recommended.

controls: Glasses:

Consider chemical goggles.

Gloves:

1.PVA 2.PE/EVAL/PE 3.TEFLON

Respirator:

Type AK-P Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)

Storage and Transportation:

Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children. Keep away from food, drink and animal feeding stuffs.

Fire/Explosion Hazard: Flammable. Toxic smoke/fumes in a fire. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point.

### **PROPERTIES**





Liquid.Flammable.









### **FIRST AID**

Swallowed:

Give water (if conscious). URGENT MEDICAL ATTENTION. Do NOT give milk or oil. Do NOT give

alcohol.

Wash with running water. Eye:

Remove contaminated clothing. Wash with soap & Skin:

Fresh air. Rest, keep warm. If breathing shallow, Inhaled:

give oxygen. Medical attention.

**Advice To** Evaluate for respiratory distress. Consider lavage

with cuffed tube. NO adrenalin.

Doctor:

Fire Fighting: Foam.

Spills and

Disposal:

Eliminate ignition sources. Prevent from entering drains. Contain spillage by any means. Absorb with dry agent. Stop leak if safe to do so. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be disposed of in a safe way. To clean the floor and all objects contaminated by this material, use water

and detergent.

# SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS



Explosive







Toxic Х

Radioactive Oxidizing

Х

- Must not be stored together