

Akzo Nobel Aerodur 37076 Primer RAL1014

INGREDIENTS	CAS NO	%	8HR OEL
methyl isobutyl ketone	108-10-1	5-10	205 mg/m3
xylene	1330-20-7	5-10	350 mg/m3
n-butyl acetate	123-86-4	10-15	713 mg/m3
propylene glycol monomethyl ether acetate, alpha-isomer	108-65-6	1-5	274 mg/m3



UN No: 1263 Hazchem Code: •3YE DG Class: 3

Subsidiary Risk: Not Applicable

Packing Group: II

Poisons Schedule: Not Applicable



NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION















Acute Health Effects: Harmful by inhalation. Irritating to respiratory system. Irritating to skin.

Risk of serious damage to eyes.

Vapours may cause drowsiness and dizziness.

Chronic **Health Effects:** May cause CANCER by inhalation.

* - limited evidence

PRECAUTIONS FOR USE













Appropriate
engineering
controls:

Local Exhaust Ventilation recommended.

Glasses:

Consider chemical goggles.

Gloves:

1.TEFLON 2.VITON 3.PE/EVAL/PE

Respirator:

Type A Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)

Storage and Transportation:

Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report. Use only in well ventilated areas. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children. Keep container in a well ventilated place. Keep away from food, drink and animal feeding stuffs. Keep away from sources of ignition. No smoking.

Fire/Explosion Hazard:

HIGHLY FLAMMABLE. Toxic smoke/fumes in a fire. Use only in well ventilated areas. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. In case of fire and/or explosion, DO NOT BREATHE FUMES.

PROPERTIES





Liquid. Highly flammable.









FIRST AID

Swallowed:

Give water (if conscious). Seek medical advice. Do NOT give milk or oil. Do NOT give alcohol.

Wash with running water (15 mins). Medical

Eye: attention.

Remove contaminated clothing. Wash with soap &

Fresh air. Rest, keep warm. If breath shallow, give Inhaled:

oxygen. Medical attention.

Advice To Doctor:

Skin:

Treat symptomatically. Evaluate for respiratory distress. Consider lavage with cuffed tube. NO

adrenalin.

Fire Fighting:

Spills and

Disposal:

Keep containers cool. Foam.

Eliminate ignition sources. Consider evacuation. Prevent from entering drains. Contain spillage by any means. Absorb with dry agent. Stop leak if safe to do so. Use only in well ventilated areas. Take precautionary measures against static discharges. Dispose of this material and its container at

hazardous or special waste collection point. This material and its container must be disposed of in a safe way. To clean the floor and all objects contaminated by this material, use water and

detergent.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS









Explosive х х

Toxic

Radioactive Oxidizing

х х

- Must not be stored together