

Dow Corning Molykote D-321 R Anti-Friction Coating

INGREDIENTS	CAS NO	%	8HR OEL
naphtha petroleum, heavy, hydrodesulfurised	64742-82-1.	10-30	790 mg/m3
n-butyl acetate	123-86-4	30-60	713 mg/m3
graphite	7782-42-5	<10	3 mg/m3
molybdenum disulfide	1317-33-5	10-30	-



UN No: 1993 Hazchem Code: •3Y DG Class: 3 Subsidiary Risk: None

Packing Group: III Poisons Schedule: \$5



NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION



















Harmful by inhalation. Harmful if swallowed.

Irritating to respiratory system.

Acute Health Irritating to skin. Effects:

Risk of serious damage to eyes.

HARMFUL-May cause lung damage if swallowed. Vapours may cause drowsiness and dizziness.

Chronic **Health Effects:** Danger of cumulative effects.

Repeated exposure may cause skin dryness and

cracking.

* - limited evidence

PRECAUTIONS FOR USE





Appropriate











engineering controls:	Local Exhaust Ventilation recommended.
Glasses:	Consider chemical goggles.
Gloves:	1.VITON 2.PE/EVAL/PE 3.PVA
Respirator:	Type A Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)
Storage and Transportation:	Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children. Keep away from food, drink and animal feeding stuffs.
Fire/Explosion Hazard:	Flammable. Toxic smoke/fumes in a fire. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste

collection point.

PROPERTIES



Liquid Flammable.

EMERGENCY









FIRST AID

Swallowed:	Give water (if conscious). Seek medical advice.
Eye:	Wash with running water (15 mins). Medical attention.
Skin:	Remove contaminated clothing. Wash with soap & water.
Inhaled:	Fresh air. Rest, keep warm. If breath shallow, give oxygen. Medical attention.
Fire Fighting:	Foam. Dry agent. Do NOT fight fire with water.
Spills and Disposal:	Eliminate ignition sources. Prevent from entering drains. Contain spillage by any means. Absorb with dry agent. Stop leak if safe to do so. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS

х х



Explosive



Toxic





and detergent.



disposed of in a safe way. To clean the floor and all objects contaminated by this material, use water

x x

- Must not be stored together