

# E-Z Weld 733 Low VOC Pipe Cleaner

INGREDIENTS	CAS NO	%	8HR OEL
cyclohexanone	108-94-1	2-15	100 mg/m3
ACETONE	67-64-1	>75	1185 mg/m3



UN No: 1993 Hazchem Code: •3YE DG Class: 3 Subsidiary Risk: None Packing Group: II

Poisons Schedule: Not Applicable



### NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

# **HEALTH HAZARD INFORMATION**













Harmful by inhalation. **Acute Health** Irritating to eyes. Effects:

HARMFUL-May cause lung damage if swallowed. Vapours may cause drowsiness and dizziness.

Harmful: danger of serious damage to health by prolonged exposure through inhalation.

Possible risk of harm to the unborn child. **Chronic Health** Repeated exposure may cause skin dryness and Effects:

> cracking. \* - limited evidence

#### PRECAUTIONS FOR USE













engineering controls:	Local Exhaust Ventilation recommended.
Glasses:	Consider chemical goggles.
Gloves:	1.BUTYL 2.PE/EVAL/PE 3.TEFLON
Respirator:	Type AX Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)
Storage and Transportation:	Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children. Keep container in a well ventilated place. Keep away from food, drink and animal feeding stuffs. Keep away from sources of ignition. No smoking.

# Fire/Explosion Hazard:

HIGHLY FLAMMABLE. Vapours/gas heavier than air. Toxic smoke/fumes in a fire. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. In case of fire and/or explosion, DO NOT BREATHE FUMES.

## **PROPERTIES**





Skin:

Liquid. Highly flammable.

#### **EMERGENCY**









## **FIRST AID**

Swallowed:	Give water (if conscious). Seek medical advice. Do
	NOT give milk or oil. Do NOT give alcohol.

Eye: Wash with running water.

Remove contaminated clothing. Wash with soap &

Fresh air. Rest, keep warm. If breathing shallow, give Inhaled:

oxygen. Medical attention.

Advice To No antidote. Supportive care. Doctor:

Fire Fighting: Keep containers cool. Foam.

> Spilled liquid has low boiling temperature and evaporates quickly. Eliminate ignition sources. Pollutant. Prevent from entering drains. Contain spillage by any means. Control vapour with water spray/ fog. Absorb with dry agent. Stop leak if safe to

Spills and Disposal: do so. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be disposed of in a safe way. To clean the floor and all objects contaminated by

this material, use water and detergent.

## SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS









Toxic Radioactive Oxidizing Explosive х Х

- Must not be stored together