

Criterion 234 Catalyst

INGREDIENTS	CAS NO	%	8HR OEL
MOLYBDENUM (VI) OXIDE	1313-27-5	10-19	10 mg/m3
cobalt (II) oxide	1307-96-6	1-5	-
ALUMINA H152, H155	1344-28-1.	74-98	10 mg/m3



UN No: 3077 Hazchem Code: 2Z DG Class: 9 Subsidiary Risk: None

Packing Group: III

Poisons Schedule: Not Applicable



NFPA Rating:

- ▶ 0: Minimum
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION





Acute Health Effects:

May cause SENSITISATION by skin contact.

Chronic **Health Effects:**

Danger of cumulative effects. Limited evidence of a carcinogenic effect. Harmful: danger of serious damage to health by prolonged exposure through inhalation and if swallowed.

* – limited evidence

PRECAUTIONS FOR USE















Appropriate engineering controls:	Local Exhaust Ventilation recommended.
Glasses:	Consider full face-shield.
Gloves:	PVC chemical resistant type.
Respirator:	Particulate. (AS/NZS 1716 & 1715, EN 143:2000 & 149:001, ANSI Z88 or national equivalent)
Storage and Transportation:	Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children.
Fire/Explosion Hazard:	Toxic smoke/fumes in a fire. Dispose of this material and its container at hazardous or special waste collection point.

PROPERTIES



Solid.Does not burn.

EMERGENCY











FIRST AID

Swallowed:	If more than 15 mins from Doctor, INDUCE VOMITING (if conscious).
Eye:	Wash with running water (15 mins). Medical attention.
Skin:	Flood body with water. Remove contaminated clothing. Wash with water
Inhaled:	Fresh air. Rest, keep warm. If breath shallow, give oxygen. Medical attention.
Advice To Doctor:	Deferoxamine is preferred chelator. Supportive care. "metal fume fever". Remove from exposure. Treatment is supportive.
Fire Fighting:	Keep containers cool. Keep surrounding area cool. Water spray/fog.
Spills and Disposal:	Pollutant. Avoid dust. Prevent from entering drains. Contain spillage by any means. Sweep shovel to safe place. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be disposed of in a safe way. To clean the floor and all objects contaminated by this material, use water and detergent.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS





Explosive Radioactive х х

- Must not be stored together