

Veolia Hydrex 4202

 INGREDIENTS
 CAS NO
 %
 8HR OEL

 BIOMATE MBC2881E
 10222-01-2
 19-21



UN No: 3265 Hazchem Code: 2X DG Class: 8

Subsidiary Risk: Not Applicable

Packing Group: III

Poisons Schedule: Not Applicable

3 10

NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION











Acute Health Effects: Harmful by inhalation. Harmful if swallowed. Causes burns.

Risk of serious damage to eyes.

May cause SENSITISATION by skin contact.

PRECAUTIONS FOR USE













Appropriate engineering controls:	General Exhaust Ventilation adequate.
Glasses:	Consider full face-shield.
Gloves:	PVC chemical resistant type.
Respirator:	Type AB-P Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)
Storage and Transportation:	Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point. Keep locked up. Keep out of reach of children. Keep away from living quarters. Keep away from food, drink and animal feeding stuffs.
Fire/Explosion Hazard:	Toxic smoke/fumes in a fire. Attacks metals to liberate hydrogen. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special

waste collection point.

PROPERTIES









EMERGENCY











FIRST AID

Swallowed:	Give water (if conscious). URGENT MEDICAL
	ATTENTION.

Eye: Wash with running water (15 mins). Medical attention.

Skin: Flood body with water. Remove contaminated clothing.

Wash with water

Inhaled: Fresh air. Rest, keep warm. If breathing shallow, give

oxygen. Medical attention.

Advice To
Doctor:

Airway problems - 100% O2. Treat burns as thermal.

Retract eyelids - irrigate 30 mins. Retract eyelids/

Irrigate 30 mins.

Fire Fighting: Water spray/ fog.

Eliminate ignition sources. Prevent from entering drains. Contain spillage by any means. Control vapour with water spray/ fog. Absorb with dry agent. Neutralize with soda ash/ lime. Stop leak if safe to do so. Use only in well ventilated areas. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be disposed

contaminated by this material, use water.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS

of in a safe way. To clean the floor and all objects





Spills and

Disposal:

Explosive Radioactive

Α....

x — Must not be stored together