

HEMPELS HEMPADURE ZINC PRIMER (MIX)

INGREDIENTS	CAS NO	%	8HR OEL
propylene glycol monomethyl ether acetate, alpha-isomer	108-65-6	10-30	274 mg/m3
xylene	1330-20-7	10-30	350 mg/m3
methyl ethyl ketone	78-93-3	10-30	445 mg/m3
zinc powder	7440-66-6	30-60	2 mg/m3



UN No: 1263 Hazchem Code: •3YE DG Class: 3

Subsidiary Risk: Not Applicable

Packing Group: II Poisons Schedule: \$5



NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION





















Irritating to eyes, respiratory system and skin. May cause SENSITISATION by skin contact.

HARMFUL-May cause lung damage if swallowed. Vapours may cause drowsiness and dizziness.

Harmful by inhalation and in contact with skin.

Chronic

Acute Health

Effects:

Health Effects:

May cause harm to the unborn child. Repeated exposure may cause skin dryness and

* - limited evidence

PRECAUTIONS FOR USE





Appropriate

Environment:



cracking.









engineering controls:	Local Exhaust Ventilation recommended.
Glasses:	Consider chemical goggles.
Gloves:	1.PE/EVAL/PE 2.PVA 3.TEFLON
Respirator:	Type A Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)
Storage and Transportation:	Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report.
Fire/Explosion Hazard:	HIGHLY FLAMMABLE. Vapours/gas heavier than air. Toxic smoke/fumes in a fire.
Environment	Very toxic to aquatic organisms. May cause long-term adverse effects in the aquatic environment. Use appropriate container to

avoid environmental contamination.

instructions/Safety data sheets.

Avoid release to the environment. Refer to special

PROPERTIES









Does not mix with water. Sinks in water. Highly flammable.

EMERGENCY









FIRST AID

Contact Doctor or Poisons Centre. Swallowed: Give glass of water.

Wash with running water (15 mins). Medical Eye: attention.

Skin: Wash with soap & water. Apply cleansing cream.

Fresh air. Rest, keep warm. If breathing shallow, Inhaled:

give oxygen. Medical attention.

Evaluate for respiratory distress. Consider lavage

Advice To with cuffed tube. NO adrenalin.

Decontaminate if necessary. CaNa2EDTA is the Doctor:

chelator of choice.

Keep containers cool. Fire Fighting:

Foam.

Eliminate ignition sources.

Consider evacuation.

Spills and Prevent from entering drains. Disposal: Contain spillage by any means.

Absorb with dry agent. Stop leak if safe to do so.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS









Explosive

Toxic Х

Radioactive Oxidizing х х

- Must not be stored together