

Axens HR-1246

INGREDIENTS	CAS NO	%	8HR OEL
MOLYBDENUM (VI) OXIDE	1313-27-5	10-25	10 mg/m3
cobalt (II) oxide	1307-96-6	2.5-10	-
ALUMINA H152, H155	1344-28-1.	>50	10 mg/m3
aluminium	7429-90-5	NotSpec	5 mg/m3



UN No: 3077 Hazchem Code: 2Z DG Class: 9

Subsidiary Risk: None Packing Group: III

Poisons Schedule: Not Applicable



NFPA Rating:

- ▶ 0: Minimum
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION













Irritating to eyes.

Irritating to respiratory system.

May cause SENSITISATION by skin contact.

Danger of cumulative effects.

Chronic Health Effects:

Limited evidence of a carcinogenic effect. Harmful: danger of serious damage to health by prolonged exposure through inhalation and if

swallowed.

* - limited evidence

PRECAUTIONS FOR USE













engineering controls:	Local Exhaust Ventilation recommended.
Glasses:	Consider full face-shield.
Gloves:	PVC chemical resistant type.
Respirator:	Particulate. (AS/NZS 1716 & 1715, EN 143:2000 & 149:001, ANSI Z88 or national equivalent)
Storage and Transportation:	Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children.
Fire/Explosion Hazard:	Toxic smoke/fumes in a fire. Dispose of this material and its container at hazardous or special waste collection point.

PROPERTIES





Solid. Does not mix with water.

EMERGENCY





Skin:

Doctor:

Spills and

Disposal:





FIRST AID

Eye: Wash with running water (15 mins). Medical attention. Flood body with water. Remove contaminated clothing.

Wash with water

Fresh air. Rest, keep warm. If breath shallow, give Inhaled:

oxygen. Medical attention.

Deferoxamine is preferred chelator. Supportive care. Advice To "metal fume fever". Remove from exposure. Treatment

is supportive.

Keep containers cool. Water spray/ fog. Fire Fighting:

> Pollutant. Avoid dust. Prevent from entering drains. Contain spillage by any means. Sweep shovel to safe place. Dispose of this material and its container at hazardous or special waste collection point. This

material and its container must be disposed of in a safe way. To clean the floor and all objects contaminated by

this material, use water and detergent.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS





Explosive Radioactive

- Must not be stored together

х