

Rust-Oleum ROJ Damp Proof Red Primer 769 Tremolite Free

INGREDIENTS	CAS NO	%	8HR OEL
Stoddard Solvent	8052-41-3.	35	790 mg/m3
talc	14807-96-6	5	3 mg/m3



UN No: 1263 Hazchem Code: •3Y DG Class: 3

Subsidiary Risk: Not Applicable

Packing Group: III Poisons Schedule: S5



NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ **3**: High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION









HARMFUL-May cause lung damage if swallowed. Vapours may cause drowsiness and dizziness.

Chronic **Health Effects:** Repeated exposure may cause skin dryness and cracking.

* - limited evidence

PRECAUTIONS FOR USE





Annronriate

Hazard:











engineering controls:	Local Exhaust Ventilation recommended.
Glasses:	Consider chemical goggles.
Gloves:	PVC chemical resistant type.
Respirator:	Type A Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)
Storage and Transportation:	Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report.
Fire/Explosion	Flammable.

Vapours/gas heavier than air.

Toxic smoke/fumes in a fire.

PROPERTIES





Liquid.Flammable.

EMERGENCY









FIRST AID

Give water (if conscious). Seek medical advice.

Swallowed: Do NOT give milk or oil. Do NOT give alcohol.

Eye: Wash with running water. Remove contaminated clothing. Wash with soap &

water.

Fresh air. Rest, keep warm. If breathing shallow, Inhaled:

give oxygen. Medical attention.

Advice To Evaluate for respiratory distress. Consider lavage

with cuffed tube. NO adrenalin. Doctor:

Fire Fighting: Foam.

Skin:

Eliminate ignition sources.

Prevent from entering drains. Spills and Contain spillage by any means.

Disposal: Absorb with dry agent.

Stop leak if safe to do so.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS









Explosive

Toxic Radioactive Oxidizing

x x x x

- Must not be stored together