

UOP GB-346S 7X14 Adsorbent

INGREDIENTS	CAS NO	%	8HR OEL
copper(II) sulfide	1317-40-4	20-50	-
copper(II) oxide	1317-38-0	0-30	-
aluminium oxide	1344-28-1.	45-80	10 mg/m3
water	7732-18-5	<10	-



UN No: **3190** Hazchem Code: **1Y** DG Class: **4.2**

Subsidiary Risk: Not Applicable

Packing Group: II

Poisons Schedule: Not Applicable

2 3 W

NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION





Effects:













Irritating to eyes, respiratory system and skin.

Chronic Health Effects:

Acute Health

Harmful: danger of serious damage to health by prolonged exposure through inhalation.

* - limited evidence

PROPERTIES







Solid. Does not mix with water. Sinks in water.R11HAG22R17

EMERGENCY









PRECAUTIONS FOR USE















Appropriate engineering controls:

General Exhaust Ventilation adequate.

Glasses:

Consider chemical goggles.

Gloves:

1.NEOPRENE 2.VITON 3.PVA

Respirator:

Particulate. (AS/NZS 1716 & 1715, EN 143:000 &

....

149:001, ANSI Z88 or national equivalent)
Store in cool, dry, protected area. Take

Storage and Transportation:

precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children.

Fire/Explosion Hazard:

Environment:

HIGHLY FLAMMABLE. Toxic smoke/fumes in a fire. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point.

Very toxic to aquatic organisms.

May cause long-term adverse effects in the aquatic environment. Use appropriate container to avoid environmental contamination.

Avoid release to the environment. Refer to special instructions/Safety data sheets.

FIRST AID

Swallowed:	If more than 15 mins from Doctor, INDUCE VOMITING (if conscious).
Eye:	Wash with running water (15 mins). Medical attention.
Skin:	Flood body with water. Remove contaminated clothing. Wash with water For burns: Apply cold water. Do NOT remove clothes from area.
Inhaled:	Fresh air. Rest, keep warm. If breath shallow, give oxygen. Medical attention.
Advice To Doctor:	Deferoxamine is preferred chelator. For severe poisoning, administer CaNa2EDTA. Supportive care. "metal fume fever".
Fire Fighting:	Water jets.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS





Spills and

Disposal:







Eliminate ignition sources. Avoid dust. Prevent from

entering drains. Contain spillage by any means.

Flammable Explosive Toxic Radioactive Oxidizing

Must not be stored together