

Hempel'S Zinc Metal Pigment 97170

INGREDIENTS	CAS NO	%	8HR OEL
ZINC AND ZINC OXIDE	1314-13-2	5-<10	5 mg/m3
zinc	7440-66-6	>90	-



UN No: 3077 Hazchem Code: 2Z DG Class: 9 Subsidiary Risk: None

Packing Group: III Poisons Schedule: Not Applicable



NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ **3**: High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION

PRECAUTIONS FOR USE









Glasses:	Consider chemical goggles.
Gloves:	Leather Gloves

Particulate. (AS/NZS 1716 & 1715, EN 143:2000 & Respirator: 149:001, ANSI Z88 or national equivalent)

Storage and Transportation:

Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report. Use only in well ventilated areas. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children. Keep container tightly closed. Keep container dry.

Fire/Explosion Hazard:

Reacts with water. Use only in well ventilated areas. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. In case of fire and/or explosion, DO NOT BREATHE FUMES.

PROPERTIES





Solid R15R17

EMERGENCY









FIRST AID

Rinse mouth with water. Swallowed: Wash with running water. Eye: Remove contaminated clothing. Wash with soap & Skin: water. For burns: Apply cold water. Do NOT remove clothes from area. Cover wound. NO OINTMENTS. Fresh air. Rest, keep warm. If breathing shallow, Inhaled: give oxygen. Medical attention.

Advice To Doctor: Supportive care. "metal fume fever". Remove from exposure. Treatment is supportive. Decontaminate if necessary. CaNa2EDTA is the chelator of choice.

Fire Fighting:

Spills and

Disposal:

Dry agent. Do NOT fight fire with BCF extinguisher.

Do NOT fight fire with water. Eliminate ignition sources. Pollutant. Avoid dust.

Prevent from entering drains. Contain spillage by any means. Sweep shovel to safe place. Use only in well ventilated areas. Take precautionary

measures against static discharges. Dispose of this material and its container at hazardous or special

waste collection point. This material and its container must be disposed of in a safe way.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS









Explosive Toxic

Radioactive Oxidizing x x x x

- Must not be stored together