

Schlumberger Thermafrac High Temperature Crosslinker J596

INGREDIENTS	CAS NO	%	8HR OEL
TRIETHANOLAMINE	102-71-6	<30	5 mg/m3
sodium borate anhydrous (Na2B4O7)	1330-43-4	<6.5	5 mg/m3
zirconyl chloride	7699-43-6	1-5	5 mg/m3

UN No: Not Applicable Hazchem Code: Not Applicable

DG Class: None Subsidiary Risk: None Packing Group: None

Poisons Schedule: Not Applicable



NFPA Rating:

- ▶ 0: Minimum
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION





Effects:







Irritating to respiratory system. **Acute Health** Irritating to skin.

Risk of serious damage to eyes.

May cause SENSITISATION by skin contact.

Limited evidence of a carcinogenic effect.

May impair fertility. Chronic

Health Effects:

May cause harm to the unborn child.

* - limited evidence

PRECAUTIONS FOR USE











		20	3

Appropri	ate
engineer	ing
contro	ols:

Local Exhaust Ventilation recommended.

Glasses:

Consider chemical goggles.

Gloves:

1.BUTYL 2.NATURALRUBBER 3.PVA

Respirator:

Type AK-P Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88

or national equivalent)

Storage and Transportation:

Store in cool, dry, protected area. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of

Fire/Explosion Hazard: Toxic smoke/fumes in a fire. Dispose of this material and its container at hazardous or special waste collection point.

Environment:

May cause long-term adverse effects in the environment.Use appropriate container to avoid environmental contamination.

Avoid release to the environment. Refer to special instructions/Safety data sheets.

PROPERTIES





Liquid, Mixes with water, Alkaline, Combustible,

EMERGENCY









FIDOT AIR

FIRST AID	
Swallowed:	If more than 15 mins from Doctor, INDUCE VOMITING (if conscious).
Eye:	Wash with running water (15 mins). Medical attention.
Skin:	Remove contaminated clothing. Wash with soap & water.
Inhaled:	Fresh air. Rest, keep warm. If breath shallow, give oxygen. Medical attention.
Advice To Doctor:	Supportive care. Irrigate eyes with saline. Supportive care.
Fire Fighting:	Water spray/ fog.
	Eliminate ignition sources. Pollutant. Absorb with dry

Spills and Disposal: agent. Stop leak if safe to do so. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be disposed of in a safe way. To clean the floor and all objects contaminated by this material,

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS

use water.





Explosive Radioactive Х

- Must not be stored together