

CRC Industries Welder'S Anti Spatter

INGREDIENTS	CAS NO	%	8HR OEL
dimethyl ether	115-10-6	20-30	760 mg/m3
Water	7732-18-5	60-70	-
white mineral oil (petroleum)	8042-47-5	1-3	5 mg/m3
1,3-dichloropropene	542-75-6	NotSpec	4.5 mg/m3



UN No: 1950

Hazchem Code: Not Applicable

DG Class: 2.1

Subsidiary Risk: Not Applicable Packing Group: Not Applicable Poisons Schedule: Not Applicable



NFPA Rating:

- ▶ 0: Minimum

- ▶ 3: High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION

PRECAUTIONS FOR USE













Appropriate
engineering
controls:

Local Exhaust Ventilation recommended.

Glasses:

Consider chemical goggles.

Gloves:

1.NATURAL+NEOPRENE 2.NITRILE

Respirator:

Type KAX-P Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or

national equivalent)

Storage and Transportation: Store in cool, dry, protected area. Use only in well ventilated areas. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children. Keep container in a well ventilated place. Keep away from heat. Keep away from sources of ignition. No smoking.

Fire/Explosion Hazard: HIGHLY FLAMMABLE. Vapours/gas heavier than air. Toxic smoke/fumes in a fire. Risk of explosion if heated under confinement. Use only in well ventilated areas. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. In case of fire and/or explosion, DO NOT BREATHE FUMES.

PROPERTIES









Liquid. Gas. Mixes with water. Extremely flammable.

EMERGENCY



FIRST AID

Skin: Wash with soap & water. Apply cleansing cream.

Fire Fighting:

Keep containers cool. Water spray/ fog.

Eliminate ignition sources. Absorb with dry agent. Stop leak if safe to do so. Use only in well ventilated areas. Take precautionary measures against static

Spills and Disposal:

discharges. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be disposed of in a safe

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS







Х



Explosive

Toxic X

Radioactive Oxidizing

- Must not be stored together