

Nalco 3D Trasar 3DT224

INGREDIENTS	CAS NO	%	8HR OEL
phosphoric acid	7664-38-2	5-10	1 mg/m3
methanol	67-56-1	<1	262 mg/m3
zinc chloride	7646-85-7	5-10	1 mg/m3



UN No: 3264 Hazchem Code: 2X DG Class: 8

Subsidiary Risk: Not Applicable

Packing Group: III

Poisons Schedule: Not Applicable



NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate

Liquid.

- ▶ 3: High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION









Harmful if swallowed. Causes burns.

Risk of serious damage to eyes.

PRECAUTIONS FOR USE













4	
 	_

Appropriate engineering controls:	General Exhaust Ventilation adequate.
Glasses:	Consider full face-shield.
Gloves:	1.NITRILE, PVC 2.PE 3.TEFLON
Respirator:	Type BAX-P Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)
Storage and Transportation:	Store in cool, dry, protected area. Restrictions on Storage apply. Refer to Full Report. Keep locked up. Keep out of reach of children. Keep away from living quarters. Keep away from food, drink and animal feeding stuffs.
Fire/Explosion Hazard:	Attacks metals to liberate hydrogen.
Environment:	Toxic to aquatic organisms. May cause long-term adverse effects in the aquatic environment. Use appropriate container to avoid environmental contamination. Avoid release to the environment. Refer to special instructions/Safety data sheets.

PROPERTIES









Mixes with water. Corrosive. Acid.Does not burn.





FIRST AID

EMERGENCY

Swallowed:	Give water (if conscious). URGENT MEDICAL ATTENTION.	
Eye:	Wash with running water (15 mins). Medical attention.	
Skin:	Flood body with water. Remove contaminated clothing. Wash with water	
Inhaled:	Fresh air. Rest, keep warm. If breathing shallow, give oxygen. Medical attention.	
Advice To Doctor:	Airway problems - 100% O2. Treat burns as thermal. Retract eyelids - irrigate 30 mins. Retract eyelids/ Irrigate 30 mins. Decontaminate with ipecac or lavage. Ethanol therapy.	
Fire Fighting:	Keep surrounding area cool. Water spray/fog.	
Prevent from entering drains. Contain spillage by any means. Absorb with dry agent. Neutralize with soda ash/ lime. Stop leak if safe to do so. This material and its container must be dispin a safe way. To clean the floor and all objects contaminathis material, use water.		

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS





Х

Explosive Radioactive

x - Must not be stored together