METALLIC WELDING POWDER 29021

INGREDIENTS	CAS NO	%	8HR OEL
aluminium	7429-90-5	0-44	10 mg/m3
copper(I) oxide	1317-39-1	0-24	-
copper(II) oxide	1317-38-0	0-24	-
C.I. Pigment Black 11	1317-61-9	0-19	-

UN No: Not Applicable

Hazchem Code: Not Applicable DG Class: Not Applicable Subsidiary Risk: Not Applicable Packing Group: Not Applicable Poisons Schedule: Not Applicable



NFPA Rating:

- ▶ 0: Minimum
- ▶ 1: Low
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION









Harmful if swallowed. **Acute Health** Irritating to eyes.

> Effects: Irritating to respiratory system.

> > Irritating to skin.

Harmful: danger of serious damage to health by **Chronic Health**

prolonged exposure through inhalation. Effects:

* – limited evidence

PRECAUTIONS FOR USE













Appropriate

engineering General Exhaust Ventilation adequate.

controls:

Glasses: Consider chemical goggles.

Gloves: PVC chemical resistant type.

Particulate. (AS/NZS 1716 & 1715, EN 143:2000 & Respirator:

149:001, ANSI Z88 or national equivalent)

Storage and **Transportation:** Store in cool, dry, protected area. Dispose of this material and its container at hazardous or special

waste collection point. Keep out of reach of children. Keep away from food, drink and animal feeding stuffs.

Fire/Explosion

Dispose of this material and its container at Hazard: hazardous or special waste collection point.

PROPERTIES







Solid. Does not mix with water. Sinks in water. Combustible.

EMERGENCY









FIRST AID

Swallowed: Rinse mouth with water.

> Wash with running water. For discomfort: Eye:

medical advice.

Remove contaminated clothing. Wash wit Skin:

water.

Inhaled: Fresh air. Rest, keep warm.

Advice To Deferoxamine is preferred chelator. For se

Doctor: poisoning, administer CaNa2EDTA.

Fire Fighting: Foam.

> Eliminate ignition sources. Avoid dust. Sw to safe place. Dispose of this material and

Spills and Disposal: container at hazardous or special waste c point. This material and its container mus disposed of in a safe way. To clean the flo objects contaminated by this material, us-

detergent.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMI





Explosive Radioactive



- Must not be stored together

For further information call Environmental Protection: 880-9714 (DH) or 427-1535 (JID). For proper disposal methods and locations chemical contaminated material, contact the Environmental Engineering Division on 880-9754	for the che