

Halliburton AS-7 Anti-Sludging Agent

INGREDIENTS	CAS NO	%	8HR OEL
MORPHOLINE	110-91-8	1-5	71 mg/m3
METHANOL	67-56-1	5-10	262 mg/m3
dodecylbenzenesulfonic acid, morpholine salt	12068-08-5	30-60	-



UN No: 2924 Hazchem Code: •3W DG Class: 3 Subsidiary Risk: 8 Packing Group: III

Poisons Schedule: Not Applicable

NFPA Rating:

- ▶ 0: Minimum
- ▶ 2: Moderate
- ▶ 3: High
- ▶ 4: Extreme

HEALTH HAZARD INFORMATION











Harmful by inhalation. Harmful in contact with skin.

Harmful if swallowed. **Acute Health** Causes burns.

> Effects: Toxic: Danger of very serious irreversible effects

through inhalation, in contact with skin and if

swallowed.

Risk of serious damage to eyes.

PRECAUTIONS FOR USE





Appropriate

engineering

Environment:







Local Exhaust Ventilation recommended.



controls:		
Glasses:	Consider chemical goggles. Consider full face-shield.	
Gloves:	1.PE/EVAL/PE 2.PVDC/PE/PVDC	
Respirator:	Type KAX Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)	
Storage and Transportation:	Restrictions on Storage apply. Refer to Full Report. Dispose of this material and its container at hazardous or special waste collection point. Keep locked up. Keep out of reach of children. Keep away from living quarters. Keep away from food, drink and animal feeding stuffs.	
Fire/Explosion Hazard:	Flammable. Toxic smoke/fumes in a fire. Dispose of this material and its container at hazardous or special waste collection point. In case of fire and/or explosion, DO NOT BREATHE FUMES.	

Toxic to aquatic organisms. Use appropriate container

to avoid environmental contamination.

PROPERTIES





Liquid, Corrosive, Flammable,

EMERGENCY











FIRST AID

If more than 15 mins from Doctor, INDUCE Swallowed: VOMITING (if conscious).

> Eye: Wash with running water (15 mins). Medical attention.

> > Flood body with water. Remove contaminated clothing.

Wash with water

Fresh air. Rest, keep warm. If breath shallow, give Inhaled:

oxygen. Medical attention.

Advice To Treat symptomatically. Decontaminate with ipecac or

Doctor: lavage. Ethanol therapy.

Fire Fighting: Foam

Skin:

Eliminate ignition sources. Prevent from entering drains. Contain spillage by any means. Absorb with dry agent. Stop leak if safe to do so. Dispose of this

Spills and material and its container at hazardous or special Disposal: waste collection point. This material and its container must be disposed of in a safe way. To clean the floor

> and all objects contaminated by this material, use water and detergent.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS











Flammable Explosive

Toxic х х

Radioactive Oxidizing х х

x — Must not be stored together